UNITEDSTATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

JUN -9 2009

FORMAI OM B No Expires

PPROVED 0 1004-0137 March 31, 2007	PA
141ai cii 51, 2007	

SUNDRY NOTICES AND REPORTS C Do not use this form for proposals to drill or abandoned well. Use Form 3160-3 (APD) for s	to re-enter an 6 If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions o	7. If their a CAIA group and Name and I'm No	
1 Type of Well Gas Well Other	8 Well Name and No	
2. Nameof Operator BOPCO, L.P.	Poker Lake Unit #145 9 API Well No	
	o (include area code) 30-015-31006 683-2277 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec, T, R, M, or Survey Description)	Nash Draw (Delaware/BS/Avalon Sand)	
NWSE 2310' FSL, 1815' FEL Sec 31, T23S, R30E	11 County or Parish, State Eddy NM	
12. CHECK APPROPRIATE BOX(ES)TO INDICATE	NATURE OF NOTICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Notice of Intent Notice of Intent Alter Casing Casing Repair Change Plans Plug and A Convert to Injection Plug Back	truction Recomplete X OtherAdd Delaware Abandon Perfs Perfs	
Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) BOPCO, L.P. respectfully wishes to report the addition of perfs in the wellbore as follows: 04/25/2009 MIRU Lucky Well Service. POOH w/ rods & pump. 04/29-04/30/2009 RIH w/ SN jts tbg & 2-1/2' sleeve on rods. POOH & LD same. Dig out & replace csg valve. 05/01/2009 MIRU BWWC & Basic Energy Services. RBIH w/ 5-1/2" CIBP + CCL to 4,000' to have CCL fail. POOH, replace CCL & RBIH. Set CIBP @ 5,925'. RBIH w/ tandem slick guns + CCL Perforated Delaware from 5,820'-5,860'. RD BWWC. RIH w/ SN & jts tbg (EOT @ 5,883'). Secure well & SDN. 05/02/2009 RU Basic Energy Services & spotted 1,000 gal of 7-1/2% NEFE HCl acid across perfs (5,820'-5,860'). POOH & SBID w/ tbg. 05/06/2009 MIRU Cudd Pumping Service. Frac'd Delaware perfs from 5,820'-5,860' w/ 38,818 gals BFRAC w/ 143,428 lbs (102,000 lbs 16/30 Ottowa + 41,428 lbs "Super LC"). 05/07/2009 RIH w/ blade bit & jts tbg, EOT @ 5,336'. RU Power swivel, wash down to CIBP @ 5,925' & circulate 3 hrs w/ 700 psi. 05/08-09/2009 POOH w/ tbg. RBIH w/ BHA, TAC & jts tbg. ND BOP, set TAC @ 5,338' w/ 12,000# tension + SN @ 5,532'. NU WH. RIH w/ remainder of rods. RDPT, RDPU. Return well to production. Best test to date on 05/11/2009: 24 BO, 259 BW, 5 MCF, TP 200 psi, LP 50 psi, CP 60 psi on wide open choke.		
Valerie Truax	Title Regulatory-Admin-Assistant	
Signature Munistruay	Date 06/02/2009 CCEPIED FUK KEUUKU	
THIS SPACE FOR FEDERAL	OR STATE OFFICE USE	
Approved by	DESCRIPTION OF LAND MANAGEMENT BY PERSON KNOWINGLY and WILLIAM TO MAKE TO SAFE TO THE UNITED TO THE	