CD-A	FORMAPPROVED ADM B No. 1004-0137 Expires: March 31, 2007	Rm
	4 Y 0 1 1 1 1 1	

SUNDRY Do not use thi	UNITEDSTATES DEPARTMENT OF THE SUREAU OF LAND MANA NOTICES AND REP DISTRIBUTION OF STATES D	INTERIOR AGEMENT PORTS ON WEL o drill or to re-en	ter an	FORMAPPROVED ADM B No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No. NMLC069140 6. If Indian, Allottee or Tribe Name	6
SUBMIT IN TRI	PLICATE - Other instru	7. If Unit or CA/Agreement, Name and/or No. NMNM68294			
1. Type of Well OilWell	8. Well Name and No.				
2. Name of Operator BOPCO, L.P.		9. API Well No			
3a. Address P.O. Box 2760 Midland T	¥ 70702	30-015-36289 10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec		7	INDIAN FLATS (ATOKA)		
NENW, 1140' FSL. 1830' FEL, SEC. 10, T22S, R28E				11. County or Parish, State EDDY NM	
12. CHECK AF	PROPRIATE BOX(ES)TO	INDICATE NATURI	E OF NOTICE, RI	EPORT, OR OTHĚR DATA	
TYPEOF SUBMISSION	OF SUBMISSION TYPE OF ACTION		EOF ACTION		
Notice of Intent Subsequent Report Final Abandonment Notice	X Acidize AlterCasing Casing Repair Change Plans Convert to Injection	Deepen FractureTreat New Construction Plug and Abandon Plug Back	Production (Sta Reclamation Recomplete Temporarily Ab Water Disposal	Well Integrity X OtherAcidize	- -
If the proposal is to deepen dire Attach the Bond under which the following completion of the in- testing has been completed. Find determined that the site is read BOPCO, LP respectfully	ectionally or recomplete horizontal the work will be performed or provivolved operations. If the operation and Abandonment Notices shall be by for final inspection.) or requests to report the Energy Services. Acidiers. RD BES.	Ily, give subsurface location vide the Bond No on file vide the Bond No on file vide the Bond No on file vide results in a multiple completified only after all requires accidization of perfect accidization of perfect Atoka perfs 1	ns and measured and treat BLM/BIA Requirection or recompletion ments, including reclans in the wellbore 1,462'-11,471' w	vith 5000 gals 7.5% HCl, with additiv	
03/29/2009 No Key We 03/29/2009 Well returne 04/01/2009 Best test to	ed to production.			0300 F3, Illaue / Tulis.	
Please note correction for Perfs were incorrectly st	or 3160-4 Well Comple ated as 11642'-11671'.	tion Report (dated	March 17, 200	9) regarding wellbore's Atoka perfs. 1471'.	=
14. I hereby certify that the fore Name (Printed/Typed)	going is true and correct	1			

Valerie Truax Title Regulatory Admin-Assistant-05/07/2009 Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE 6 2009 JUN Title Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office BUREAU OF LAND MANAGEMENT which would entitle the applicant to conduct operations thereon Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)