Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources	SEP 1 8 2009 Form C-103 June 19, 2008
District I 25 N. French Dr , Hobbs, NM 88240	Lifergy, winterars and ivaluat resources	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-015-23906 5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
District IV 1220 S St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name Platt PA
PROPOSALS.)	Gas Well Other	8. Well Number 5
Name of Operator Yates Petroleum Corporation		9. OGRID Number 025575
3. Address of Operator 105 South Fourth Street, Artesia, N	M 88210	10. Pool name or Wildcat Atoka-Yeso
4. Well Location	2310 feet from the South line and	1650 feet from the West line
Section 26	Township 18S Range 26E	NMPM Eddy County
	11. Elevation (Show whether DR, RKB, RT, GR, etc. 3313'GR	c.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF IN	TENTION TO: SUI	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON ☐ REMEDIAL WO	RK ALTERING CASING
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS COMMENCE DI MULTIPLE COMPL CASING/CEME	RILLING OPNS.□ PANDA □ NT JOB □
DOWNHOLE COMMINGLE	MOETH EL COMI E	NI JOB
OTHER: OTHER:		
	leted operations. (Clearly state all pertinent details, a rk). SEE RULE 1103. For Multiple Completions: A	
or recompletion.	, 2221022 11000 1011000p.	
Yates Petroleum Corporation plans t	o plug and abandon this well as follows:	
1. MIRU all safety equipment as ne		
2. Set a 4-1/2" CIBP at 2661' and cap with 25 sx Class "C" cement. This will place a plug from 2321'-2661' across the Glorieta top over the perforations.		
3. Circulate hole with salt gel mud. Spot 25 sx cement plug across the intermediate casing shoe from 1000'-1340'. WOC and tag plug,		
reset if necessary. 4. Spot 25 sx cement plug across the surface casing shoe from 0-300'. WOC and tag plug, reset if necessary.		
	ole marker and clean location as per regulated.	,
NOTE: Yates Petroleum Corporation	n will use steel pits and no earth pits	Notify OCD 24 hrs. prior To any work done.
		lo any work done
Spud Date:	Rig Release Date:	40119.
I hereby certify that the information	above is true and complete to the best of my knowled	lge and belief.
/ A: 1	_	
SIGNATURE ()	TITLE Regulatory Compliance Sur	•
Type or print name Tina Huer For State Use Only	^	
APPROVED BY:	TITLE Approval Granted p	providing work 121/09 DATE 9/21/CIS
Conditions of Approval (if any):	19 Complete D)	



