Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR

***	. O 2000
1	FOR
	OME
OCD Artesia	Exnire

M APPROVED 007

ia	OMB N	0 1004-013	
	Expires N	March 31, 2	

BUREAU OF LAND MA SUNDRY NOTICES AND REF Do not use this form for proposals abandoned well. Use Form 3160-3 (PORTS ON WELLS to drill or to re-enter an	5 Lease Serial No. NMLC0709386 If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Oth	er instructions on page 2.	7 If Unit of CA/Agreement, Name and/or No.
1. Type of Well ✓ Oil Well Gas Well Other 2 Name of Operator NEARBURG PRODUCING CO		8 Well Name and No CC FEDERAL #3 9 API Well No. 30-015-33548
3a. Address 3300 N 'A' ST , BLDG 2, STE 120 MIDLAND, TX 79705	3b. Phone No. (include area code) (432) 818-2950	10 Field and Pool or Exploratory Area NE RED LAKE; GL-YE 96836
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Descriptudes 25 SL & 532 FWL SEC 9, 18-S, 27-E	on)	11. Country or Parish, State EDDY Co, NM
12. CHECK THE APPROPRIATE I	BOX(ES) TO INDICATE NATURE OF NO	OTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
Notice of Intell	Alter Casing	Fracture Treat	Reclamation	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
	Change Plans	Plug and Abandon	Temporarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	

roposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

8/19/09 Notify BLM Kent Caffall

8/20/09 Tag CIBP @ 1,850'. Circulate 10# MLF. Spot 25sx cmt @ 1,850' to 1,610'. Spot 25sx cmt @ 1,254'.

8/21/09 Tag TOC @ 1,000'. Circulate 10sx cmt @ 100' to surface.

Remove wellhead, anchors, install P&A marker, backfill cellar.

Accepted as to plugging of the well bore. Liability under bond is retained until Surface restoration is completed.

Same of the second

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed) Randall Minear Title P&A Supervisor 08/31/2009 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE

Approved by 15 2009 Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would Office entitle the applicant to conduct operations thereon

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any Benarios of agency of the fictitious or fraudulent statements or representations as to any matter within its jurisdiction

CARLSBAD FIELD OFFIC

(Instructions on page 2)