N.M. Oil Cons. DIV-Dist. 2

1301 W. Grand Avenue

FORM APPROVED OMB No. 1004-0137

Form 3	160-5
(Augus	t 20%)
	,

Form 3160-5 i (August 2000)	UNITED STATE PARTMENT OF THE EAU OF LAND MAN	S INTERIOR	Arte	sia, I	١M	88210 5. Lease Serial ?	OME Expir	M APPF 3 No. 100 es: July			-
SUNDRY N Do not use this i	NOTICES AND REPO form for proposals t Use Form 3160-3 (A	ORTS ON W	re-en	ter an oosals.	,	NM-102906 6. If Indian, Alk	ottee or T	ribe Nar	ne		
SUBMI	T IN TRIPLICATE - Other	instructions or	n page 2			7. If Unit of CA	/Agreeme	nt, Nav	band/orN	AVEL	
1. Type of Well Oil Well Gas V	Vell Other		,			8. Well Name at Thunderhead		1	NOV 1	6 2009	\dashv
2. Name of Operator Primero Operating, Inc.					-,	9. API Well No. 30 005 64114			OCD A	RTESI	A
3a. Address PO Box 1433, Roswell, NM 88202-1433		3b. Phone No.	•	area code,)	10. Field and Po		loratory	Area	,	
4. Location of Well (Footage, Sec., T., 1980 FSL, 660' FEL, Section 9, 74S, R27E	R.,M., or Survey Description			:		11. Country or F Chaves, New	-	ite		,	
12. CHEC	CK THE APPROPRIATE BO	OX(ES) TO IND	ICATE N	ATURE (OF NOTI	CE, REPORT OR	OTHER	DATA			
TYPE OF SUBMISSION				TYPE	OF AC	TION				·	
Notice of Intent	Acidize Alter Casing		ure Treat		Rec	duction (Start/Resu	me)	□ we	iter Shut-Of	r	
✓ Subsequent Report	Casing Repair Change Plans	==	Construct and Abane	.,		complete		L_ Oth	ner		
Final Abandonment Notice	Convert to Injection	Plug		1011		ter Disposal				- ,	
Pump 6 sx Clas October 22, 2009: RIH w/ one joint November 5, 2009: Cut well head o	ss C plug at 3700', WOC 3 ss c plug at 1560', WOC 3 s C plug at 60', open casin tubing, tag cement at 31.	2 hours and RII 3.5 hours and Fing valve and co 5', RDMO Pulling	H and ta RIH and t ement fel ng Unit.	g cement ag cemer I, Cemen	@ 3435 at @ 976 t pump l	5' 3' broke so could no	ot fill cas	ing.	d cement	g @ 3700°.	
See Well Bore A		n surface as ne	eded.	. IS	WELL DO	D AS TO PLUGGING OF RE LIABILITY UNDER 3 UNTIL SURFACE RESTO IS COMPLETED	CKO	OB <73408	2009 NO	$\overline{\mathcal{H}}$	
14. I hereby certify that the foregoing is t Phelps White	rue and correct. Name (Printe	ed/Typed)	Title P	resident					ģ		
Signature			Date 1	1/04/2009)			DAHO SOUND	3		
	THIS SPACE	FOR FEDE	RAL O	R STA	TE OF	FICE USE		7.1. 2	80		
Approved by /S/ DA		199	Tit	le PET	ROLE	UM ENGINEE	R Date	2	NOV 0	C 2009	
Conditions of approval, if any, are attached that the applicant holds legal or equitable tentitle the applicant to conduct operations	itle to those rights in the subje thereon.	et lease which wo	ould Of			LL FIELD OF					
Title 18 U.S.C. Section 1001 and Title 43 fictitious or fraudulent statements or representations.				vingly and	willfully	to make to any dep	artment or	agency	of the Unite	d States any	false,
(Instructions on page 2)											



Well Bore Diagram

Well Name: Field:

CIBP + cmt @ 5950', 10/20/09

Thunderhead Federal Unit #1

Wildcat, Strawn

Last Update: 25-Jun-09

10/21/2009

9-Jul-09 TD

P&A Date: 10/21/09

Spud Date:

Log Tops

San Andres 1236 Glorietta 2400 2506 Abo Wolfcamp 5248

40' 14" conductor

T. Penn 3-Bros 5930 Strawn 6316 Mississippian 6586

6820

Top of Cement @ 1140'

1508' 8 5/8" 24# J-55 ST&C

680 sx 60/40C, 200sx Class C+2%CaC1, circulated

TD

Depth	Deviation
498	1/2
965	1
1508	3/4
1994	2 3/4
2153	3
2248	1 1/2
2366	2 3/4
2493	1 1/4
2754	1
3222	1
4245	1
4774	3/4
5220	1/4
5799	1/2
6369	1/2
-	

Perfs 5998-6008, 2spf 9/8/09

Perfs 6054-62, 2spf 9/8/09

Acidize 5998-6008, 6054-62 w/ 1500 gals 9/14/09, zones swab some burnable gas, little entry.

Perforations: 6312 - 32, 1 SPF, 9/8/09

Acidize 1500 gal 9/8/09, Swab Dry

CIBP @ 6380', 9/8/09

Perforations: 6404 to 6424', August 26, 2009

Acidize w/ 2000 gals 7.5% NEFE 8/28/09 Swab Dry, No Show oil or gas

CIBP Set @ 6485' w/ 35' cement. 8/26/09

Perforations: 6498 to 6508', July 29, 2009

Perforations produced naturally. Well tests indicate very limited reservoir. Perfs plugged back 8/26/09

PBTD @ 6713'

6799 5 1/2" 17# J and K

1215 sx 50-50-10C+1/8#CF+6%FL-52A+, 305 sx 50-50-2C+5%Salt+.5%FL-52A+.3%CD-32

TD @ 6820, 7/9/09

