				•					
Submit 3 Copies To App Office	ropriate District	State of	of New Me	exico				F	Form C-103
District I	Energy, Minerals and Natural Resources				; <u></u>	June 19, 2008			
	French Dr., Hobbs, NM 88240					WELL API NO.			
District II 1301 W. Grand Ave., Art	tesia. NM 88210	OIL CONSERVATION DIVISION				30-015-30889  5. Indicate Type of Lease			
District III		1220 South St. Francis Dr.			3	STATE STEE			
1000 Rio Brazos Rd., Az District IV	tec, NM 87410	Santa Fe, NM 87505				6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., S 87505	Santa Fe, NM		,			. 0		30000 1101	
SUNDRY NOTICES AND REPORTS ON WELLS						7. Lease N	lame or U	nit Agree	ment Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH						KERSEY STATE			
PROPOSALS.)	IR. USE "APPLIC	AHON FOR PERMIT" (FC			1				
1. Type of Well: Oil Well Gas Well Other RECEIVED						8. Well Number #2			
2. Name of Operato	NOV	<b>2 4</b> 2009	9	OGRIE	Number	255333			
LIME ROCK RESOURCES A, L.P. NUV Z 4 2005  3. Address of Operator						10. Pool name or Wildcat: (03230)			
c/o Mike Pippin LLC, 3104 N. Sullivan, Farmington, NM 8MMOCD ARTESIA						Artesis, Queen-Grayburg-San Andres			
4. Well Location						**************************************			
Unit Letter	<u>P:</u> :	844 feet from the	SOUTH	_ line and330	0	_feet fror	n theI	EAST	line
Section	32	Township	17-S	Range 28-E	N	<b>IMPM</b>	Eddy (	County	
		11. Elevation (Show 3670' GL	whether DR,	RKB, RT, GR,	etc.)		, , ,		
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON    TEMPORARILY ABANDON   CHANGE PLANS    PULL OR ALTER CASING   MULTIPLE COMPL    DOWNHOLE COMMINGLE				SUBSEQUENT REPORT OF:  REMEDIAL WORK					
OTHER: Perf & Stin	nulate More Sai	n Andres	$\boxtimes$	OTHER:					
of starting ar or recomplet Lime Rock plans a sar 2718'). PT 5-1/2" csg frac w/about 36,000#	ny proposed workon ion. me zone workon g to 500 psi. Pe 16/30 & 15,000	ver as follows: TOH werf additional Q-G-SA 0# 12/20 sand in 25# Xods & initiate producir	For Multiply/rods, pump @ about 219 (-linked gel.	e Completions: , & tbg. Set a C 9'-2421'. Brea CO after frac &	: Attacl CBP @ akdown	h wellbore 2470' (at perfs w/	e diagram pove existi about 2500	of proposing SA per 0 gal 15%	ed completion rfs @ 2514'- NEFE acid &
SIGNATURE	Milot	77	lete to the be	eum Engineer -	edge ar		DATE	11/23/09	
Type or print name For State Use Only	Mike Pippin	E-n	nail address:	mike@pip	pinlle.c	com	PHONE	: _ <u>505-32</u> '	<u>/-4573</u>

TITLE\_\_\_

APPROVED BY: Conditions of Approval (if any)

DATE 1/185/09