## HNEED STATES

_	
DEC	4 2009
A LE ADMINI	WITTER

X Other

Add Pay

Form 3160- 5	UNITEDSTATES			INMOUNTARTESIA				
August (2007)	DEPARTMENT OF THE INTERIOR			ONIB Na 1001-0137				
	BUREAU OF LAND	D MANAGEMENT Expires July 31.		1 spires July 31, 2010				
SU	NDRY NOTICES AND	REPORTS ON V	VELLS	5 Lease Serial No NMLC028731A				
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6 H Indian, Allottee or Firbe Name				
SUBMIT IN TRIPLICATE - Other Instructions on page 2		7 If Unit or CA. Agreement Name and/or No.						
Type of Well				NMNM111789X				
Oil Well Gas Well	Other	•		8 Well Name and No				
Name of Operator				Dodd Federal Unit #82				
	Marbob Fnergy Corpora	ition		9 API Well No				
3a Address		3b Phone No tinci	lude area code)					
PO Box 227 Artesia, NM - 88211-0227		(575)	(575) 748-3303	30-015-29757  10 Tield and Pool or Exploratory Area				
		(373)	/40-3303					
1 Location of Well (Locage Sec	L. R. M. or Survey Description)			Grbg Jackson; SR-Q-Grbg-SA				
1750 PCL 000 PPL C . 22 T170 D20P 11 5 1			11 County or Parish, State					
1750 FSL 990 FEL, Sec. 22-T17S-R29E, Unit I		Eddy Co., NM						
12 CHECK APPRO	PRIATE BOX(S) TO INDIC	CATE NATURE OF	NOTICE, REPO	ORT, OR OTHER DATA				
TYPE OF SUBMISSION		TYPE OF ACTION						
Notice of Intent	Acidize	Deepen	Production (	Start/ Resume) Water Shut-off				
•	Altering Casing	Fracture Treat	Reclamation	Well Integrity				

**OCD** Artesia

X Recomplete

Water Disposal

Temporarily Abandon

13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamation have been completed, and the operator has determined that the site is ready for final inspection.)

New Construction

Plug and Abandon

Plug Back

Added pay in the Yeso (2) zone as follows:

10/22/09 - MIRU

Subsequent Report

10/23/09 - POOH w/ rods & tbg Perf the Yeso (2) @ 4653' - 4851' (19 shots).

Convert to Injection

10/26/09 - Acdz w/ 2000 gal NE Fe 15% HCl.

10/29/09 - RHH w/ 157 jts 2 7/8" tbg. Set @ 4885'. RIH w/ pump & rods. Hang well on pump. RDMO Producing Interval: Yeso @ 4016' - 4851'.

14. Thereby certify that the foregoing is true and correct						
Name (Printed Typed)						
	litle					
Dianast Bilggs	Production Manager					
	r	ACCEPTED FOR RECORD				
Surature 10000	Date	IAC:(	:FPTFN	FUD DE	MADA	]
			ントニンのたける	par antadae	UUUU	
THIS SPACE FOR FEDE	ERAL OR STATE	DFFIG	E USE		7	
			DEO	2		
Approved by	Little	ز	DEC	9 <sub>□.</sub> 2009	1	
Conditions of approval if any are attached. Approval of this notice does not warran	it or	7	s/ Dusti	n Winkle	24	
certify that the applicant holds legal or equitable title to those rights in the subject is	case Office	· L			1 1	
which would entitle the applicant to conduct operations their	con	BIJ	REALLOFIA	ND MANAGEN	ACAIR	
Tale 18 U.S.C. Section 1001 AND Tale 43 U.S.C. Section 1212 make a acrime	for any octson known;	gly and	CARLSRAD	FIEND MECIA	Or rectic	of the United
States any talse fectitious or fraudulent statements or representations as to any matter	within its jurisdiction		CHALODAD	TILLU OFFICE		