N.M. Oil Cons. DIV-Dist. 2

OF THE INTER	1301	<b>VV.</b>	Glain	JA	yenu	OMB No
r of the inter	UOR	:-	NINA	QΩ	210	Expires Nov

EDADEM CENTE OF THE DITEDIO			OMB NO 1004-0133
PEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT ARTESIA.	NINA O	0010	Expires November 30,2000
RUREAU OF LAND MANAGEMENT ARCSIA.	IAINI O	OZ Lease Ser	ial No

DEC	31	2009 <sub>SUN</sub>	PRY NOTICES	AND REPORTS	S ON WELLS
		Do not us	a this form for	nronocale to dril	ll or to recentor

NMOCD ARabandored well. Use Form 3160-3 (APD) for such proposals

6. If Indian, Allottee or Tribe Name

NM-58803

SUBMIT IN TRIPLICATE - Other Instructions on reverse side		7. If Unit or CA/Agreement, Name and/o No.	
I Type of Well  ☑ Oil Well ☐ Gas Well ☐ Other	, , , , , , , , , , , , , , , , , , ,	8 Well Name and No	
2 Name of Operator		COBRA FEDERAL #2	
ARMSTRONG ENERGY CORPORATION		9. API Well No.	
3a. Address	3b Phone No. (include area code)	30-005-63735	
P.O. BOX 1973 ROSWELL, NM 88202-1973	575-625-2222	10 Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey De	scription)	COMANCHE DRAW	
1710' FSL & 950' FWL, SEC 19, T11S,R27E		11. County or Parish, State CHAVES COUNTY, NM	

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OF SUBMISSION	TYPE OF ACTION				
	Acidize	☐ Deepen	Production (Start/Resume)	☐ Water Shut-Off	
Notice of Intent	☐ Alter Casing	Fracture Treatment	Reclamation	☐ Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
	Change Plans	Plug and Abandon	Temporarily Abandon	· ·	
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Water Disposal		
12 Describe Described Occurrence (1-1) state 11 at a 11 at a 11 at a 12 at a 1					

10/20/09 SET CIBP @ 6150' WITH 25 SACKS ON TOP

10/21/09 RIH AND DUMP 5 BAILER RUN TAG @ 6123'

10/23/09 RIH AND PUMP 25 SACKS @ 6123' - TAG @ 5597'

10/26/09 SET 2<sup>ND</sup> CIBP @ 5110' SPOT 25 SACKS ON TOP

10/27/09 SPOT 25 SACKS @ 2359' - SPOT 25 SACKS @ 1195'

10/28/09 PULL 500' OF 5.5" CASING - SPOT 50 SACKS @ 550' - TAG @ 312'

10/29/09 CIRCULATE 20 SACKS FROM 65' TO SURFACE

10/30/09 - RIH AND TAG @ 312' - CIRCULATE 81 SACKS TO SURFACE - HELD 350# -RIH AND TAG @ 12' – OK'ED BY BLM

INSTALL DRY HOLE MARKER - CLEAN UP LOCATION

APPROVED AS TO PLUGGING OF THIS WELL BORE LIABILITY UNDER BOND

	IS RETAINED UNTIL SURFACE RESTORATION IS COMPLETED				
14 I hereby certify that the foregoing is true and correct Name (Printed/Typed) Bruce A. Stubbs	Titl	<sup>e</sup> Vice Presid	lent - On	erations	
Signature 3 Stubble	Dat	Date 10/30/2009			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by /S/ DAVID R. GLASS	3	PETROLEUM EN	GINEER	Date DEC 18 2009	
Need Surface Reclaimed Within 6 Months	rant or certify that i would entitle the	, 1			
And Final Abandonment Notice (FAN) Submitted By 04-30-2010.	for any person knowingly and willfully to make to any department or agency of the United States any its jurisdiction.				

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposedvork and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports shall be file within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)