

Submit 3 Copies To Appropriate District Office  
District I  
1625 N French Dr , Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd , Aztec, NM 87410  
District IV  
1220 S. St Francis Dr , Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
June 19, 2008

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-015-36433
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Turkey 4 State
8. Well Number 2
9. OGRID Number 6137
10. Pool name or Wildcat North Turkey Track; Morrow
11. Elevation (Show whether DR, RKB, RT, GR, etc ) 3412' GL

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS )	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	
2. Name of Operator Devon Energy Production Co., LP	
3. Address of Operator 20 North Broadway, OKC OK 73102-8260	
4. Well Location Unit Letter <u>L</u> : <u>1330</u> feet from the <u>south</u> line and <u>670</u> feet from the <u>West</u> line Section <u>4</u> Township <u>19S</u> Range <u>29E</u> NMPM Eddy County, NM	
11. Elevation (Show whether DR, RKB, RT, GR, etc ) 3412' GL	

RECEIVED  
JAN 25 2010  
NMOCD ARTESIA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER ADD MORROW PAY ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12/16/2009 – 12/29/2009:

RUPU. TOH w/ tbg, run gauge ring. Work pkr, wouldn't unset. Work bit/scrapper through DV tool. Set CBP at 10,960' (just above packer). RIH & perforate @ 10,659'-10,664'; (4SPF) 20 holes. PU pkr, RIH pkr @ set @ 10,582'. Tst csg 1000# - ok. Swab. Frac dwn 2 3/8" tbg w/12,500# terraprop + 20/40 snd + 406 bbls linear gel. Open chk, flw bck. Swab. Put well back onto production.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Sr. Staff Engineering Technician DATE 01/21/2010

Type or print name Stephanie A. Ysasaga E-mail address: Stephanie.Ysasaga@dvn.com PHONE: 405-552-7802

For State Use Only

APPROVED BY: [Signature] TITLE Geologist DATE 1/26/2010

Conditions of Approval (if any):