## Form 3160-5 (April 2004)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

# OCD-ARTESIA

FORM APPR	ROVED
OMB NO 10	04-0137
Expues March	31, 200

CUNDOV	NOTICES	AND	DEDODEC	011	WELLO
SUNDAY	NOTICES	LINA	REPORTS	ON	WHILS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

abandoned well. Use	JUN - 9	2010			
SUBMIT IN TRIPLICAT	TE - Other instructions	on reverse side		7 It Un NAME Proment. No.	
I Type of Well  X Oil Well Gas Well Other				8 Well Name and No North Indian #1	
2 Name of Operator	atta. Janama Dahi	ncon (15 022)		Basin Unit	
OXY USA WTP LP 3a. Address	attn: Jereme Robi	3b Phone No ( <i>include a</i>	rea code)	9 API Well No	
P.O. Box 4294, Houston, TX 772	1	(713) 366-31	L	30-015-28068 10. Field and Pool, or Explorat	orv Aiea
4 Location of Well (Footage, Sec., T., R., M., or Su				South Dagger Draw/Upp	
UL "H" 1980' FNL & 825' FEL			-		
Sec. 2, T-21-S, R-23-E Lat: 32.50903 Long: 104.56646		1	11 County or Parish, State		
12. CHECK APPROPRIA	ATE BOX(ES) TO INDI			Eddy County	NM
TYPE OF SUBMISSION	T BOX(EG) TO INDI		<del></del>	III, ON OTHER DATA	
TTPE OF SUBMISSION		11	PE OF ACTION		
X Notice of Intent	Acidize	Deepen	Production (	Start/Resume) Water Shut-	-Off
<b>—</b>	Alter Casing	Fracture Treat	Reclamation	Well Integrit	ıy
Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
Final Abandonment Notice	Change Plans	Plug and Abandon	X Temporarily	Abandon	
	Convert to Injection	Plug Back	Water Dispos	sal	
testing has been completed. Final Abandoning determined that the final site is ready for final in the second state of the seco	The T/A for a period to recomplete 40+ omplete a determined is successful OXY will T/A and MIT test the by Marathon Oil 6/22	et 0: 7366 w/10' od of 4 years wit wells in an uppe number of wells P&A well. in regards to thi e well per rules 2/2009. Passed M (Y has a detailed ED FOR	of cmt on top h an annual r r zone. The over the cour s project on s at the recomment IT 5/29/2009 work plan in	re-up of the T/A state time requested will ase of 4 years to inc. 5/26/2010 at the BLM asendation of the BLM asee attached chart	us. allow lude and or
				Olivit	
14 Thereby certify that the foregoing is true and cor Name (PrintedTyped)  Jereme Robinson	ICCI	Title	atory Analyst		
A A -					
- FIVE	THIS SPACE FOR FEDE	Date 05/11/			
Approved by /s/ JD Whitlock		Tall		Date &	
		UFF	7	17/10	
Conditions of approval, if any, are attached. Appro- certify that the applicant holds legal or equitable till which would entitle the applicant to conduct operatio	le to those rights in the subjec	t lease Office	,		

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

#### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

T . , ,

- a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
- b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leakoff will be evaluated.
- c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval <u>with well bore</u> diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

NIBU #13. Well is approved to be TA/SI for a period of 1 Year ending 6/7/2011. This will be the last and only TA/SI approval until an approved plan of operations is submitted and approved for wells in Indian Basin. Well must be P&A or plans to return to beneficial use submitted by June 7, 2011. No MIT is required, last performed 5/29/2009 with no bleed off.