8 Submit 3 Copies To Appropriate District	State of New Mexico				Form C-103
Office District I	Energy, Minerals and Natural Resources			WELL API NO.	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240	<b>3.</b> <i>.</i>				
District II	OIL CONSERVATION DIVISION			30-015-32682	
1301 W. Grand Ave., Artesia, NM 88210	<del></del> · · ·			5. Indicate Type of	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.				✓ FEE □
District IV	Santa Fe, NM 87505			6. State Oil & G	as Lease No.
1220 S. St. Francis Dr., Santa Fe, NM					1
87505	GEG AND DEDODTE ON	WIEL L C	<del></del>	7 I same Nomes on	Unit Agreement Name:
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name of	Omt Agreement Name.
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				Porterhouse State	Com
PROPOSALS.)				rontemouse state	Com.
1. Type of Well:					
Oil Well Gas Well	Other	RECEI	VED		
2. Name of Operator				8. Well No.	
CHI OPER	CHI OPERATING, INC. FFR 0 4 7		2004		<b>#1</b>
3. Address of Operator		OCD AD	TECIA	9. Pool name or V	Wildcat
P.O. BOX 1799, MIDLAND,	TEXAS 79702	OCD-AR	IESIA		
4. Well Location					
Unit Letter A; 660	feet from the NORTH	line and 660	feet from	the EAST line	
,					
Section 32		8S Range		NMPM	County EDDY
	10. Elevation (Show wh	ether DR, RKB	3, RT, GR, etc.	)	
11. Check A	Appropriate Box to Ind	icate Nature	of Notice, F	Report or Other	Data
NOTICE OF IN		Į.		SEQUENT REI	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	□ REM	EDIAL WORK		ALTERING CASING
_		_			
TEMPORARILY ABANDON	CHANGE PLANS	☐ COM	MENCE DRIL	LING OPNS.	PLUG AND
<u></u>		_			ABANDONMENT
PULL OR ALTER CASING	MULTIPLE		ING TEST AN	D 🗆	
	COMPLETION	CEM	IENT JOB	•	
OTHER:		ОТН	IER· Co	mpletion	
OTTIER.				mpietion	
12. Describe proposed or complete	d operations. (Clearly state		etails and giv	e pertinent dates in	acluding estimated date of
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or					
recompilation.		P. C C C C P. C C C C C C C C C C C C C		roor <b>o arag</b> rami or p	reposed completion of
6/18/03, moved in & started complete	ion. Perfd 12.104-106': 12	.094-100': 12.0	070-80'-4spf (	90deg. A/1500 gals	s 5% NEFE Morrow acid
w/1000scf N2/bbl & w/65 balls, AT					
11,923-33'-4spf 90 deg. Pmpd 35 bb					
ATP-7850#, 7bpm; ISIP-6525#; 5mi	n-6974#: 10min-6809#: 15	min-6750#. Pm	npd 2 bbls 2%	KCL. Perfd 11.84	8-56'. 11.804-810'.
Hooked up gas line, 7/14/03 on 48/6					0 00 , 11,00 . 010 .
10	.,,		🔾,	,	
I hereby certify that the information	above is true and complete	to the best of n	ny knowledge	and belief	
	l.	10 410 0000 01 11	ime wieuge	una conor.	
SIGNATURE 1000 W	UW T	ITLE REGU	JLARTORY (	CLERK	DATE 1/30/04
Type or print name ROBIN ASKEW Telephone No. 432-685-5001					
	w W. Sum	i en	UPERVISOR.		
Space for State ase,	a within	30	UPBRVBUK,	NIBIANA CE	FEB 0 5 2004
APPPROVED BY	Ti	TLE			DATE
Conditions of approval, if any:					D1110
11					