Form 3160-5 (September 2001)

190 · .

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135

NMLC-028990B

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or re enter an abandoned well. Use Form 3160-3 (APD) for such proposals

Expires January 31, 2004

5. Lease Serial No.

abandoned well. Use Form 3160-3 (AFD) for Such proposals.		o. Il Indian, Allottee of Thoe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side		7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well  X Oil Well  Gas Well  Other	RECEIVED FFR 1 9 2004	8. Well Name and No.  Creek AL Federal #11
2. Name of Operator Yates Petroleum Corporation	OCD-ARTESI	9. API Well No.
	e No. (include area code)	30-015-20720
105 S. 4th Str., Artesia, NM 88210	505-748-1471	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec.,T.,R.,M., OR Survey Description)		Shugart Yates 7Rivers Qeen Grayburg  11. County or Parish, State
1650'FNL and 660'FEL of Section 25-T18S-R30	E (Unit H, SENE)	Eddy County, New Mexico
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION		
Acidize		Start/Resume) Water Shut-Off
Notice of Intent Alter Casing	Fracture Treat Reclamation	<b>=</b> "'
X Subsequent Report	New Construction Recomplete	X Other Status
Change Plans	Plug and Abandon Temporarily	Abandon Update
Final Abandonment Notice Convert to Injection	Plug Back Water Dispo	sal
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  11/21-12/4/03 RU and laid down joints of tubing. Rack 118 joints - 2-7/8". Tally in. Tagged at 2889'. Opened well and picked up 4-1/16" overshot and 2-3/8" grapple in 3-1/2" jars, bumper sub and 4-3-1/2" drill collars, 85 joints 2-7/8". Tagged at 2887'. Tried to fish and couldn't. Circulated well and started milling at 2887'. Milled out 2'. Closed BOP and circulated bottoms up. Opened well and broke circulation. Fished jar on fish came loose. Opened well and tagged at 3582'. Drilled out to 3664'. Opened well, break circulation. Start drilling at 3664'-3670'. Circulated bottoms up. POOH with 107 - 2-7/8" joints and 6 - 3-1/2" drill collars and 4-3/4" drill bit. RIH with 6 - 3-1/2" drill collars and 102 - 2-7/8" joints above perfs. Closed BOP and shut down. Opened well and run 6 joints in. RU swivel and start to mill at 3670'-3729'. Circulated bottoms clean. Pulled 7 joints out. Closed BOP and shut down. RIH with 3 joints and tag on casing walls. Run up and down at 3670' and run tubing to 3728'. Laid down 107 joints 2-7/8" tubing and 6 - 3-1/2" drill collars and shoe on bottom. Nippled down BOP. Rigged down.  Well put back on production for 1 month to evaluate.		
14. I hereby certify that the foregoing is true and correct  Name (Printed/Typed)	·	
Tina Huerta	Title Regulatory Complia	ance Supervisor
Signature 1 Hunta	Date February 11, 2004	
THIS SPACE FOR FED	ERAL OR STATE OFFICE USE	
Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrar certify that the applicant holds legal or equitable title to those rights in the subject leads to which would entitle the applicant to conduct operations thereon.	t or pase Office	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willbully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction		