OCD-ARTESIA

UNITED STATES Form 3160- 5 FORM APPROVED (August, 2007) DEPARTMENT OF THE INTERIOR OMB No. 1004-0137 BUREAU OF LAND MANAGEMENT Expires: July 31, 2010 Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee, or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA. Agreement Name and/or No. SUBMIT IN TRIPLICATE - Other Instructions on page 2. NMNM109712 Type of Well Oil Well X Gas Well 8. Well Name and No. Other Name of Operator Butterfinger Fee Com #2 Marbob Energy Corporation API Well No. 3a Address 3b. Phone No. (include area code) PO Box 227 30-015-33170 (575) 748-3303 Artesia, NM 88211-0227 10. Field and Pool, or Exploratory Area Location of Well (Footage, Sec., T., R., M., or Survey Description) Carlsbad; Morrow, South 11. County or Parish, State 1980 FSL 660 FEL, Sec. 10-T22S-R27E, Unit I Eddy Co., NM 12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Acidize Deepen Production (Start/ Resume) Water Shut-off Altering Casing Fracture Treat Reclamation Well Integrity New Construction Casing Repair Subsequent Report Recomplete Change Plans Temporarily Abandon Plug and Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports-shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 1064 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed and the operator has determined that the site is ready for final inspection.) NOV 29 2010 Marbob Energy Corporation proposes to perforate, acidize & test the Atoka and/or Strawn zones as follows: NMOCD ARTESIA Set CIBP + 35' cmt @ 11340' Atoka 10968' - 11280' (40 shots) 5000 gal NE Fe 15% HCl acid APPROVED Set CIBP + 35' cmt **OR** 10K composite frac plug @ 10925' 10346' - 10668' (47 shots) 5000 gal NE Fe 15% HCl acid 0 2010 NOV JAMES A. AMOS SUPERVISOR-EPS ***Filed w/ OCD on 3/3/09 Approved 3/6/09 14. I hereby certify that the foregoing is true and correct. Name (Printed/ Typed) Title Diana J. Briggs Production Manager Signatui Date November 5, 2010 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Conditions of approval, if any are attached. Approval of this notice does not warrant o certify that the applicant holds legal or equitable title to those rights in the subject lease Office entitle the applicant to conduct operations

Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Emil 1160-3 UNITED STATES PORMAPPROVED DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drift or to re-enter an abandoned well. Use Form \$160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other Instructions on page 2. 1. Type of Well			•				
DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Expense liny 31, 2010			OCD-ART	ESIA			
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (490) for such proposals. SUBMIT IN TRIPLICATE - Other Instructions on page 2. 1. I spec of Well Color Student In Instructions on page 2. Name of Operater Marbob Energy Corporation 3a. Address PO Box 227 Artesia, NM 88211-0227 Activities NM 88211-0227 4. Lecinosia of Well (Primage, New, 7, R. Al. or Disrupty (Inscription)) 12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF SUBMISSION Activities Production (Start/Resume) Water Shate-off (Insured Primage) Water Shate-off (Insured Primage) Water Shate-off (Insured Primage) Water Shate-off (Insured Primage) Water Shate-off (Insured Proposal to to depend inscribinally attentionally, give subscribes locations and anosatured and treat vertical and the file of any proposed over the file of the proposal to to depend inscribinally in recompletion or recomplete insurance and the site is ready for final suspection.) Marbob Energy Corporation proposes to perforate, acidize, test & possibly frac the Penn and/or Wolfcamp zones as follows: Dump 35' cmt on CIBP @ 10925' to abandon the Atoka. Set CIBP + 35' cmt @ 10325' to abandon the Strawn. Penn 10031' - 10226' (60 shots) 4pproved 6/9/10	Form 3160- 5	UNITED ST				FORM APPROVED	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drift or for re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other Instructions on page 2. 1. Type of Well	(August, 2007)	DEPARTMENT OF THE INTERIOR			OMB No. 1004- 0137		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other Instructions on page 2 1. ispected well		5.			Expíres: July 31, 2010		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3169-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other Instructions on page 2. 1. Type of Walt	SUN				5. Lease Serial N	No.	
Type of Well Son Well On Well Construction Son Well On Well Construction Son Well Son Well Construction Son Well Son Well Construction Son Well	Do not use this form for proposals to drill or to re-enter an					ittee, or Tribe Name	
Same of Operator	SUBMIT IN TRIPLICATE - Other Instructions on page 2.						
Marbob Energy Corporation 3a. Address PO Box 227 Artesia, NM 88211-0227 (575) 748-3303 Plean No. (Introductures conde) 1b. Fled and Proof, or Exploratory Area Carlsbaad, Strawn (Gas) 11. Country or Purish, State Eddy Co., NM 12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Altering Casing Practive Treat Reclamation Water Shut-off Altering Casing Repair New Construction Recentation Water Disposal 13. Describe Proposed or Completed Operation (clearly state all perturent details including estimated stating date of any proposed word and practically and actions and an ameaured and true vertical depair of the proposed is to deepen disposite for complete nor the invested eparations. If the operation results in a multiple completion or completion of the invested eparations. If the operation results in a multiple completion or completed in a destruction of the site is ready for final Abandonment Notice stating has been completed Final Abandonment Notice shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Marbob Energy Corporation proposes to perforate, acidize, test & possibly frac the Penn and/or Wolfcamp zones as follows: Dump 35' cmt on CIBP @ 10925' to abandon the Atoka. Set CIBP + 35' cmt @ 10325' to abandon the Strawn. Penn 10031' - 10226' (60 shots) 2850 gal NE Fe 15% HCl acid APPROVED ***Filed w/ OCD on 5/28/10 Approved 6/9/10		Other			R. Well Name an	nd No.	
3a. Address PO Box 227 Artesia, NM 88211-0227 4. Location of Well (Findings, Sec., T. R. M., or Survey Description) 1980 FSL 660 FEL, Sec. 10-T22S-R27E, Unit 1 12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent	·					erfinger Fee Com #2	
Artesia, NM 88211-0227 4. Location of Well (Pioutoge, Sec. T., R. M., or Survey Description) 1980 FSL 660 FEL, Sec. 10-T22S-R27E, Unit 1 12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent	2 Allman						
Artesia, NM 88211-0227 Location of Well (Finalage, Sec., T. R., M., or Survey Description) 1980 FSL 660 FEL, Sec. 10-T22S-R27E, Unit 1 12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent		ox 227		, i		30-015-33170	
Location of Well (Fourage, Ne., T., R. M., or Nurvey Description) Carlsbad; Strawn (Gas)			(575) 74	48-3303			
12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION Acidize					Carls	sbad; Strawn (Gas)	
12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent	1000 E0	Y 660 EEL Cas 10 TOOC	D27E 11::+1	Ī			
TYPE OF SUBMISSION TYPE OF ACTION	1980 F3	5L 000 FEL, Sec. 10-1225	-K2/E, UIII I		l	Eddy Co., NM	
Notice of Intent	12. CHECK APPROF	RIATE BOX(S) TO INDICA	ATE NATURE OF 1	NOTICE, REPORT	r, or othei	R DATA	
Altering Casing Fracture Treat Reclamation Well Integrity	TYPE OF SUBMISSION		TY	PE OF ACTION			
Subsequent Report Casing Repair New Construction Recomplete Polic CTIVED Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal	X Notice of Intent	Acidize	Deepen	Production (Sta	rt/ Resume)	Water Shut-off	
Change Plans		Altering Casing	Fracture Treat	Reclamation		Well Integrity	
Final Abandonment Notice	Subsequent Report	Casing Repair	New Construction	X Recomplete		RECEIVED	
13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and appropriate duration lift the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of permind markets and Sanda Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.) Marbob Energy Corporation proposes to perforate, acidize, test & possibly frac the Penn and/or Wolfcamp zones as follows: Dump 35' cmt on CIBP @ 10925' to abandon the Atoka. Set CIBP + 35' cmt @ 10325' to abandon the Strawn. Penn 10031' - 10226' (60 shots) 2850 gal NE Fe 15% HCl acid If Penn to be permanently abandoned, set CIBP + 35' cmt @ 10000'. Wolfcamp 9588' - 9874' (19 shots) 4000 gal NE Fe 15% HCl acid APPROVED ***Filed w/ OCD on 5/28/10 Approved 6/9/10		Change Plans	Plug and Abandon	Temporarily Ab	andon	NOV 9 3 2010	
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of the hirthest band saids and the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.) Marbob Energy Corporation proposes to perforate, acidize, test & possibly frac the Penn and/or Wolfcamp zones as follows: Dump 35' cmt on CIBP @ 10925' to abandon the Atoka. Set CIBP + 35' cmt @ 10325' to abandon the Strawn. Penn 10031' - 10226' (60 shots) 2850 gal NE Fe 15% HCl acid If Penn to be permanently abandoned, set CIBP + 35' cmt @ 10000'. Wolfcamp 9588' - 9874' (19 shots) 4000 gal NE Fe 15% HCl acid APPROVED ***Filed w/ OCD on 5/28/10 Approved 6/9/10	· ·	'		-			
zones as follows: Dump 35' cmt on CIBP @ 10925' to abandon the Atoka. Set CIBP + 35' cmt @ 10325' to abandon the Strawn. Penn 10031' - 10226' (60 shots) 2850 gal NE Fe 15% HCl acid If Penn to be permanently abandoned, set CIBP + 35' cmt @ 10000'. Wolfcamp 9588' - 9874' (19 shots) 4000 gal NE Fe 15% HCl acid NOV 2 0 2010 ***Filed w/ OCD on 5/28/10 Approved 6/9/10	If the proposal is to deepen dire Attach the Bond under which the following completion of the invol- testing has been completed. Fina	ctionally or recomplete horizontally, work will performed or provide the ved operations. If the operation rest I Abandonment Notice shall be file	give subsurface location e Bond No. on file with alts in a multiple comple	ns and measured and to the BLM/ BIA. Requi- tion or recompletion in	rue vertical dept red subsequent ro a new interval,	ns of periment triarkers and sands, eports shall be filed within 30 days a Form 3160-4 shall be filed once	
Penn 10031' - 10226' (60 shots) 2850 gal NE Fe 15% HCl acid If Penn to be permanently abandoned, set CIBP + 35' cmt @ 10000'. Wolfcamp 9588' - 9874' (19 shots) 4000 gal NE Fe 15% HCl acid NOV 2 0 2010 ***Filed w/ OCD on 5/28/10 Approved 6/9/10		tion proposes to perforate,	, acidize, test & po	ossibly frac the Po	enn and/or V	Volfcamp	
Wolfcamp 9588' - 9874' (19 shots) 4000 gal NE Fe 15% HCl acid NOV 2 0 2010 ***Filed w/ OCD on 5/28/10 Approved 6/9/10		9				on the Strawn.	
	Wolfcamp 9588' - 9874' (19 shots) 4000 gal NE Fe 15% HCl acid				l r	NOV 20 2010	
	14. I hereby certify that the foregoing is Name (Printed Typed)	, true and correct.					

Title Diana J. (Brig Production Manager Date November 5, 2010 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by

Conditions of approval, if any are attached. Approval of this notice does not warrant or Title Date certify that the applicant holds legal or equitable title to those rights in the subject lease of the would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.