Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103
District 1	Energy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. 30-015-24462
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	7. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE STEE
District IV	Santa Fe, NM 87505	7. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	SRO SWD
PROPOSALS.)	CATION FOR PERMIT" (FORM C-101) FOR SUCH	SKO SWD
1. Type of Well: Oil Well	Gas Well Other SWD	8. Well Number
	Out Well Other Style	103
2. Name of Operator		9. OGRID Number
COG Operating LLC 3. Address of Operator		229137 10. Pool name or Wildcat
2208 W. Main Street, Artesia, N	√M 88210	SWD; Delaware
4. Well Location	The state of the s	
Unit Letter M:	660 feet from the South line and 660	feet from the <u>West</u> line
Section 17	Township 26S Range 28E	NMPM Eddy County
	11. Elevation (Show whether DR, RKB, RT, GR, etc.,) A TO THE PARTY OF STREET
- Miles	3083' GR	The state of the s
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON REMEDIAL WOR CHANGE PLANS COMMENCE DRI	
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMEN	
DOWNHOLE COMMINGLE	MOETH EE COIM E	
OTHER:	☐ OTHER: Re	-Entry Operations (SWD)
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of		
starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed		
completion or recompletion.		
10/7/10 MIRU.		
10/8/10 PU 7 7/8" bit & drill out cmt plug. Tag 2 nd cmt plug @ 465'.		
10/11/10 Drill thru 2 nd cmt plug. Fell out of cmt @ 610'. Test csg to 1000# - ok. Tag 3 rd cmt plug @ 1795'. Circulate clean.		
10/12/10 Drill thru 3 rd cmt plug. Drill down to top of 5 ½" stub. Circulate hole.		
10/13/10 to 10/18/10 Tag top of 5 ½" stub @ 1871'. Dress off 1 ½'. Circulate clean. Mill down 26" between 5 ½" & 8 5/8" csg. Pull off stub. Circulate hole. Continue dressing between 5 ½" & 8 5/8" csg.		
10/19/10 Ran 48 jts 5 ½" 17# J-55 csg to 1874'. Cmt w/300 sx Class C Neat.		
10/20/10 to 11/2/10 Tag & drill out	DVT. Test csg to 1000# - ok. Continue drilling thru p	olugs & CIBP. Clean out to 5810'. Circulate well
clean. 11/3/10 to 11/5/10 Perforate Delaware 2961-5644' (832).		
11/8/10 Acdz Delaware w/10000 ga		
11/17/10 Ran 2 7/8" 6.5#, J-55 Duc	14738 gal fluid. line tbg & 5 ½" 10-K AS1-X NP pkr to 2900'. Performulus to 525# for 30 mins. Passed test. SWI. RD. Clean	ned MIT for State. O CD representative Darold
Gray witnessed test. Pressured annu	ulus to 525# for 30 mins. Passed test. SWI. RD. Clear	n location. RECEIVED
KEADY TO INSCE	1.	NOV 2 2 2010
		140 4 22 2010
Spud Date: 10/7/10 Re-	Entry Rig Release Date:	NMOCD ARTESIA
Thereby and Called the Configuration of the	Air and a second and a second at the second	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE		
Type or print name Stormi Davis E-mail address: sdavis@conchoresources.com PHONE: 575-748-6946		
APPROVED BY: PULLAN (NOW TITLE COMPLIANCE OFFICER DATE 12/9/10		
APPROVED BY: (if any):	THE CONFCIANCE (TYPICOR DATE 14 1/10 PX
1 I (1 1/10