Office State of New Mexico	REC'D DEC 28 2010 Form C-103
<u>District I</u> Energy, Minerals and Natural Resou 1625 N. French Dr., Hobbs, NM 88240	rces October 13, 2009 WELL API NO.
District II OIL CONSERVATION DIVISION OIL CONSERVATION DIVISION DIVISIONI DIVISIO	ON 30-015-01289
District III 1220 South St. Francis Dr	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	STATE FEE  6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	o. State on & Gas Boase No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	EAST RED LAKE UNIT TRACT 1
1. Type of Well: Oil Well Gas Well Other	8. Well Number 002
2. Name of Operator TANDEM ENERGY CORPORATION	9. OGRID Number 10068
3. Address of Operator	10. Pool name or Wildcat
11490 WESTHEIMER RD, STE. 1000 HOUSTON, TX 77077	RED LAKE;QUEEN-GRAYBURG, EAST
4. Well Location	
Unit Letter L: 1980 feet from the S line and 660 Section 36 Township 16S Range 28E	
Section 36 Township 16S Range 28E  11. Elevation (Show whether DR, RKB, RT,	
12. Check Appropriate Box to Indicate Nature of	Notice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDI	AL WORK ALTERING CASING
	NCE DRILLING OPNS.☐ P AND A ☐
PULL OR ALTER CASING   MULTIPLE COMPL   CASING DOWNHOLE COMMINGLE	CEMENT JOB
	*
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:	etails, and give portinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.	ltiple Completions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' – TAG @ 805'	ltiple Completions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' – TAG @ 805'  11/23/10 CIRCULATE 28 SACKS TO SURFACE	ltiple Completions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' – TAG @ 805'	ltiple Completions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' – TAG @ 805'  11/23/10 CIRCULATE 28 SACKS TO SURFACE	Itiple Completions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' – TAG @ 805'  11/23/10 CIRCULATE 28 SACKS TO SURFACE	RECEIVED  JAN 10 2011
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' – TAG @ 805'  11/23/10 CIRCULATE 28 SACKS TO SURFACE	RECEIVED  JAN 10 2011
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' – TAG @ 805'  11/23/10 CIRCULATE 28 SACKS TO SURFACE	Itiple Completions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' – TAG @ 805'  11/23/10 CIRCULATE 28 SACKS TO SURFACE	RECEIVED  JAN 10 2011
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' – TAG @ 805'  11/23/10 CIRCULATE 28 SACKS TO SURFACE	RECEIVED  JAN 10 2011
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' – TAG @ 805'  11/23/10 CIRCULATE 28 SACKS TO SURFACE	RECEIVED  JAN 10 2011
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' – TAG @ 805'  11/23/10 CIRCULATE 28 SACKS TO SURFACE  TINSTALL PA MARKER – CLEAN LOCATION	RECEIVED  JAN 10 2011
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' – TAG @ 805'  11/23/10 CIRCULATE 28 SACKS TO SURFACE INSTALL PA MARKER – CLEAN LOCATION  Spud Date:  Rig Release Date:	RECEIVED  JAN 10 2011  NMOCD ARTESIA
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' – TAG @ 805'  11/23/10 CIRCULATE 28 SACKS TO SURFACE  TINSTALL PA MARKER – CLEAN LOCATION	RECEIVED  JAN 10 2011  NMOCD ARTESIA
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' – TAG @ 805' 11/23/10 CIRCULATE 28 SACKS TO SURFACE TINSTALL PA MARKER – CLEAN LOCATION  Spud Date:  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my SIGNATURE Away Fully and Survey Full Paraduction.	RECEIVED  JAN 10 2011  NMOCD ARTESIA
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' - CIRCULATE PLUGGING MUD - SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' - TAG @ 805' 11/23/10 CIRCULATE 28 SACKS TO SURFACE INSTALL PA MARKER - CLEAN LOCATION  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my location suggested by the starting of the second of t	RECEIVED  JAN 10 2011  NMOCD ARTESIA  Knowledge and belief.  Knowledge Arter 1-4-2011
of starting any proposed work), SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' - CIRCULATE PLUGGING MUD - SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' - TAG @ 805' 11/23/10 CIRCULATE 28 SACKS TO SURFACE TINSTALL PA MARKER - CLEAN LOCATION  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my support of the second of	RECEIVED  JAN 10 2011  NMOCD ARTESIA  Knowledge and belief.  Knowledge and belief.  Knowledge Arter 1-4-2011  MARTING STATES STATE 1-4-2011  MARTING STATES STATE 1-4-2011  MARTING STATES STAT
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TO 11/23/10 CIRCULATE 28 SACKS TO SURFACE INSTALL PA MARKER – CLEAN LOCATION  Spud Date:  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my SIGNATURE August TITLE Product  SUSAN  Type or print name Felicety E-mail address:  Stelicety Ophlene  Approved for plushing and on the starting and on the start	RECEIVED  JAN 10 2011  NMOCD ARTESIA  Knowledge and belief.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.  11/23/10 TAG CIBP @ 1617' - CIRCULATE PLUGGING MUD - SPOT 25 SACKS ON TO 11/23/10 SPOT 25 SACKS @ 1150' - TAG @ 805' 11/23/10 CIRCULATE 28 SACKS TO SURFACE  INSTALL PA MARKER - CLEAN LOCATION  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my SIGNATURE  SIGNATURE  TITLE  Approved for pill Lisking under to Conditions of Approval (if any):  APPROVED BY:  Approved for pill Lisking under to Conditions of Approval (if any):  TITLE  Approved for pill Lisking under to Conditions of Approval (if any):  TITLE  Approved for pill Lisking under to Conditions of Approval (if any):  TITLE  Approved for pill Lisking under to Conditions of Approval (if any):  TITLE  Approved for pill Lisking under to Conditions of Approval (if any):  TITLE  Approved for pill Lisking under to Conditions of Approval (if any):  TITLE  Approved for pill Lisking under to Conditions of Approval (if any):	RECEIVED  JAN 10 2011  NMOCD ARTESIA  Knowledge and belief.