Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103		
District I	Energy, Minerals and Natural Resources		October 13, 2009 WELL API NO.		
1625 N. French Dr., Hobbs, NM 88240 District II	OH CONGEDUATION DIVIGION		30-015-21813		
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease		
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE		
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505		6. State Oil & Gas Lease No. K6261		
87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name State CU		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Numbe	8. Well Number #1	
2. Name of Operator			9. OGRID Number		
Premier Oil & Gas Inc.			017985		
3. Address of Operator			10. Pool name or Wildcat		
PO Box 1246, Artesia, NM 88211-1246			Burton Flat; Morrow		
4. Well Location					
Unit LetterB :660 feet from theNorth line and1980 feet from theEAST line					
Section 36 Township 20S Range 27E NMPM Eddy County					
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
3290' GR					
	,				
12. Check A	appropriate Box to Indicate Na	ature of Notice,	Report or Othe	er Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRI		ILLING OPNS.	P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB 🔲	•	
DOWNHOLE COMMINGLE					
OTHER:		OTHER: Cor	mpletion	.	
	eted operations. (Clearly state all p			ates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
12/16/2010: MIRU Totem Well Service, RIH with 4.375" gauge ring/JB and went down to 10,970'. RIH to 10,900'. Set CIBP at 10,900'. Mix 2 sx cement and dump onto plug. Mix 2 sx cement, load into bailer, dump 2 nd bailer onto plug for total of 35' cement on CIBP. SDFN.					
12/18/2010: RU Black Warrior wireline and perforate Atoka Lime 10634 – 10,644 (40 shots) with 2-1/8" hollow steel carrier through-tbg guns. RU swab and swab until sunset.					
12/20/2010: RU Halliburton and Basic kill truck. Pump 660 gals NE Fe 15% HCL acid followed by 67 bbls of fresh water. Zone is non-					
commercial.					
				RECEIVED JAN 10 2011 OCD ARTESIA	
	1	<u> </u>			
Spud Date:	Rig Release Da	te:			
				IECEIVE JAN 10 2011 CCD ARTES	
				 	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE TITLE Vice President Engineering DATE 1/6/2011					
Type or print name Daniel Jones E-mail address: dan.jones@premieroilgas.com PHONE:					
For State Use Only					
APPROVED BY:	M TITLE G	cologis	D	ATE 1/12/2011	