Form 3160-5 (August 2007)

N.M. Oil Cons. DIV-Dist. 2 1301 W. Grand Avenue

UNITED STATES

DEPARTMENT OF THE INTERIOR Artesia, NM 88210

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137

SUNDRY NOTICES AND REPORTS ON WELLS

Expires July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				5. Lease Serial No. NM-96205	
				6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2.				7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well				NMNM114028	
Oil Well X Gas Well Other				8. Well Name and No.	
2. Name of Operator				Frisbee BIF Federal Com #1	
Yates Petroleum Corporation				9. API Well No.	
3a. Address 3b. Phone No. (include area code)				30-005-6381	0
105 S. 4th Str., Artesia, NM 88210 575-748-1471				10. Field and Pool	or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., OR Survey Description)				Greenfield;Wolfcamp, South	
Surface - 660'FSL & 660'FEL of Section 33-T13S-R27E (Unit P, SESE)				11. County or Parish, State	
BHL - 660'FNL & 778'FEL of Section 33-T13S-R27E (Unit A, NENE)				Chaves County, New Mexico	
12. CHECK APPROPI	LATE BOX(ES) TO I	NDICATE NATURE O	F NOTICE, RE	PORT, OR OT	HER DATA
TYPE OF SUBMISSION	BMISSION TYPE OF ACTION				
					NV SI OFF
	Acidize	Deepen	Production (S	start/ Resume)	Water Shut-Off
Notice of Intent	Alter Casing	Fracture Treat	Reclamation		Well Integrity
X Subsequent Report	Casing Repair	New Construction	Recomplete		X Other Corrective
	Change Plans	Plug and Abandon	Temporarily t	Abandon	action to Notice
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dispos	al	of Violation Letter
testing has been completed. Final Abandonme determined that the site is ready for final inspect. 12/8/10 Picked up contamina	tion.	and farm. Cleaned loo		ed and the operator ha	ıs
NOTE: Was not a casing leak	Programmer .		ACCE	EPTED FO	R RECORD
	R	ECEIVED			
EED 00 2011				KEB 1/0	2011
FEB 2 2 2011				NE Parid V	NM /
	NM	OCD ARTESIA	(4	ATURAL RES	SOURCE IST
14. I hereby certify that the foregoing is true Name (<i>Printed/Typed</i>)	and correct				
Tina Hu	ierta .	Title Requ	latory Complia	nce Superviso	or
11					
Signature Charlet	THIS SPACE E	Date Janu: OR FEDERAL OR STATE	ary 25, 2011 OFFICE USE		
Approved by	THIO OF AULT		J. 110E 00E		
Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office					
which would entitle the applicant to conduct of Title 18 U.S.C. Section 1001 and Title 43 U.S.	operations thereon.		and willfully to make to	NMOCD o any department of	JAC 7 kg

any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

PAUL H



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Pecos District Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201-2019 www.blm.gov/nm/st/en.html



JAN 1 2 2011

In Reply Refer To:

Case/Lease Number: NMNM-96205

3160(NMP0130)

Order No. 04-029-11W

RECEIVED

CERTIFIED MAIL--RETURN RECEIPT REQUESTED

7006 3450 0001 4285 6126

JAN 14 2011

YPC MAIL ROOM

Yates Petroleum Corporation 105 South 4th Street Artesia, NM 88210

JAN 1 8 2019

NOTICE OF ORDERS OF THE BLM AUTHORIZED OFFICER CTION DEPARTMENT RECEIVED

Gentlemen:

An inspection was performed on Federal Lease NMNM-96205, Frisbee BIF Federal Com #1, API No.: 30-005-63810, 660 FSL & 660 FEL, SE¼SE ¼ Section 33, T. 13S., R. 27E., Chaves County, New Mexico. It was found that the location has not been maintained in a manner designed to protect the mineral resources, other natural resources, and environmental quality (43 CFR 3162.5).

ORDERS OF THE AUTHORIZED OFFICER

Pursuant to Federal Regulation 43 CFR 3162.5-1(b) which states "The operator shall exercise due care and diligence to assure that leasehold operations do not result in undue damage to surface or subsurface resources or surface improvements..." the following environmental compliance problems were identified during the latest inspection of the subject location. Specifically:

• Environmental Problem No. 1: WELL CASING IS LEAKING PRODUCED WATER

Corrective Action: The well casing needs to be repaired and all stained soil on the location shall be excavated and disposed of at an authorized disposal facility. Excavated areas shall be backfilled with clean earthen material and re-contoured to mirror the contours of the surrounding terrain.

Keep all reclamation work within the archaeological survey area of record for the Frisbee BIF Federal Com #1 location. The survey of record documents a 600' X 600' survey area with the

well bore at the center of the surveyed area. The stub/pad access road has a 100' wide surveyed corridor.

Report your compliance with this Written Order on a Subsequent Sundry Notice on Form 3160-5 (Sundry Notice and Reports on Wells) stating the above problems have been corrected and are ready for inspection, an original and 5 copies are required.

In accordance with 43 CFR 3163.1(a), please comply with the corrective action(s) for the identified environmental problems no later than **February 28, 2011** after receipt of this Written Order. If you fail to comply within the time frames specified, you will be subject to further enforcement action as may be deemed necessary.

WARNING

Orders of the Authorized Officer or Incidents of Non Compliance and reporting time frames begin upon receipt of the Notice or 7 business days after the date it is mailed, whichever is earlier. Each problem or violation must be corrected within the prescribed time from receipt of this Notice and reported to the Bureau of Land Management office at the address shown above.

For Incidents of Non Compliance, please note that you already may have been assessed for noncompliance (see amount under "Assessed for Noncompliance"). If you do not comply as noted above under "Corrective Action to Be Completed By," you may incur additional assessment under (43 CFR 3163.1) and may also incur Civil Penalties (43 CFR 3163.2). All self-certified corrections must be postmarked no later than the next business day after the prescribed time for correction.

Note: Section 109(d)(1) of the Federal Oil and Gas Royalty Management Act of 1982, as implemented by the applicable provisions of the operating regulations at Title 43 CFR 3163.2(f)(1), provides that any person who "knowingly or willfully" prepares, maintains, or submits false, inaccurate, or misleading reports, notices, affidavits, records, data, or other written information required by this part shall be liable for a civil penalty of up to \$25,000 per violation for each day such violation continues, not to exceed a maximum of 20 days.

REVIEW AND APPEAL RIGHTS

A person contesting an order of the authorized office or violation must request a State Director Review of the Order or Incident of Noncompliance. This request must be filed within 20 working days of receipt of the Order or Incident of Noncompliance with the appropriate State Director at PO Box 27115, Santa Fe, NM 87502-0115 (see 43 CFR 3165.3). The State Director review decision may be appealed to the Interior Board of Lands Appeals, 801 North Quincy Street, MS 300-QC, Arlington, Virginia 22203 (see 43CFR 3165.4). Contact the above listed Bureau of Land Management office for further information.

If you have any questions concerning our Written Orders for the Frisbee BIF Federal Com #1 location, please contact Jared Reese, Natural Resource Specialist at the Roswell Field Office at 575-627-0249.

Sincerely,

Angel Mayes

Assistant Field Manager, Lands and Minerals


1- Archaeological Survey Limits (1p) Enclosures


Enclosure 1


Archaeological Survey Limits


For your information the archaeological survey of record for the Frisbee BIF Federal Com #1 location documents a 600' X 600' survey area with the well bore at the center of the surveyed area. The stub/pad access road has a 100' wide surveyed corridor. If the previously surveyed area is not large enough to provide a remediation and reclamation work area an additional archaeological survey to current BLM standards of the additional work surface needed is required and must be approved by BLM in writing before surface disturbance occurs.


WELL SIGN -LOCATION















WEUHEAD-PUMPJACK







FACILITIES 12/07/10





WESTSIDE OF LOCATION





-

