

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

JUL 22 1974

O. C. C.

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
2. Name of Operator FRANKLIN, ASTON & FAIR, INC.		8. Farm or Lease Name Edelweiss
3. Address of Operator P. O. Box 1090, Roswell, New Mexico 88201		9. Well No. 1
4. Location of Well UNIT LETTER A , 990 FEET FROM THE North LINE AND 990 FEET FROM THE East LINE, SECTION 35 TOWNSHIP 5S RANGE 26E NMPM.		10. Field and Pool, or Wildcat Wildcat (Devonian)
15. Elevation (Show whether DF, RT, GR, etc.) 4044.2' GL		12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pursuant to telephone conversation with Mr. Carl Uvolg June 19, 1974, this well was plugged and abandoned June 29, 1974 as follows:

Set cast iron bridge plug at 5,830 feet, spotted 15 sacks cement plug and circulated hole with heavy mud. *TD 6731*

Pulled tubing and shot 4½ casing at 2,460 feet and pulled.

Re-ran tubing and spotted 35 sack cement plug at 2,460-2,360 feet.
35 sack cement plug at 1,400-1,300 feet
In and Out of the 8 5/8 surface casing
20' plug and marker at surface.

Cementing work done by Halliburton.

*Casing left in hole
8 5/8" - 1356 - 700 circ.
4 1/2" - from 2460 to 6231*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Grant M. Smith* TITLE Geologist DATE July 16, 1974

APPROVED BY *Selma M. ...* TITLE OIL AND GAS INSPECTOR DATE DEC 10 1975

CONDITIONS OF APPROVAL, IF ANY:

