

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
Midwest Federal 0223201

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Midwest Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Sams Ranch

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 9, T14S, R28E,
Hagerman Area

12. COUNTY OR PARISH 13. STATE

Chaves New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL GAS WELL OTHER

SEP 10 1973

2. NAME OF OPERATOR
R. L. Foree

3. ADDRESS OF OPERATOR
3700 First National Bank Bldg., Dallas, Texas O.C.C. ARTESIA OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface 990' FSL & 660' FEL, Sec. 9, T14S, R28E,
Chaves County, New Mexico

14. PERMIT NO.
12-14-1972

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
GR 3570 DF 3576

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) Perforating

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-13-73: Perforated 2 shots per foot 1713-16 and 1698-1700. Tested cement job. Found had no cement job. Squeezed perforations with 25 sacks cement. Drilled out cement.

8-17-73: Re-perforated 2 shots per foot 1696-98 and 1712½-15½. Acidized with 750 gallons mud acid, 75 gallons U-66, 36 ball sealers, 1 high pressure ball injector and 2 gallons A-170 inhibitor. Cement job broke down during acid job.

RECEIVED
AUG 31 1973
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

R. L. Foree

TITLE

Agent

DATE

August 28, 1973

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE

SEP - 6 1973
R. L. BEERMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side