

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 41-1424.

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <u>Dry</u>		5. LEASE DESIGNATION AND SERIAL NO. <u>NM-2581</u>	
2. NAME OF OPERATOR <u>*Fossil Fuels Inc. (Jack L. McClellan-Lessee of Record)</u>		6. IF INDIAN, ALLOTTEE OR TRIBAL NAME	
3. ADDRESS OF OPERATOR <u>P.O. Drawer 730, Roswell, New Mexico 88202</u>		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) <u>At surface</u>		8. FARM OR LEASE NAME <u>Federal #1</u>	
14. PERMIT NO.		9. WELL NO. <u>1</u>	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>3589' G.L.</u>		10. FIELD AND POOL, OR WILDCAT <u>Sams Ranch</u>	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 11-T14S-R28E</u>	
		12. COUNTY OR PARISH <u>Chaves</u>	13. STATE <u>N.M.</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to plug and abandon this hole as follows:

Pull 4-1/2" casing @ free point. Spot 100' plug @ total depth. 100' plug over stub of 4-1/2" casing. 100' plug in and out of 8-5/8" casing (243'). 15 sx plug at surface. Heavy mud will be pumped between plugs. Place dry hole marker and restore surface.

* ALL PLUGS ARE TO BE A MINIMUM OF 255X

*Fossil Fuels Inc. is a defunct corporation and as lessee of record, Jack L. McClellan is plugging and abandoning this test

NOV 12 1981
O. C. D.
ARTESIA, OFFICE

RECEIVED
NOV 8 1981

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Mark J. Gillham
(This space for Federal or State office use)
APPROVED PETER W. CHESTER
Sgd. NOV 10 1981
FOR
JAMES A. GILLHAM
DISTRICT SUPERVISOR

TITLE Geologist DATE 10-30-81
TITLE _____ DATE _____

*See Instructions on Reverse Side