Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-10	
District I	Energy, Minerals and Natural Resources		Revised March 25, 199	9
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
District II 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		30005-60291 5. Indicate Type of Lease	\dashv
District III	2040 South Pacheco			
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.	\dashv
2040 South Pacheco, Santa Fe, NM 87505			0. State Off & Gas Lease No.	
Santa Fe, NWI 87505 Santa Fe, NWI 87505 Sundry Notices and Reports on Wells (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUGBACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Injection			7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICA"	FION FOR PERMIT" (FORM C-10	OI) FOR SUCH	Twin Lakes San Andres Unit	
1. Type of Well:			<u> </u>	
On wen - Gas wen -	Other Injec	QLOIL /	1 05 1	
2. Name of Operator		RECEIVED		
Concho Oil & Gas Corp. 3. Address of Operator		OCD - ARTESIA	No Hool name or Wildcat	\dashv
110 W. Louisiana Ste 410; Midland,	Tx 79701	Å.	Twin Lakes; San Andres (Assoc)	
4. Well Location		\$39397 July		
Unit Letter O: 330 F	eet from the South	line and2310fee	et from the <u>East</u> line	
Section 36		lange 28E	NMPM Chaves County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3846 GR				
11. Check Ap	propriate Box to Indicat	e Nature of Notice,	Report or Other Data	
			SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK \square	PLUG AND ABANDON 🔲	REMEDIAL WOR	K ALTERING CASING [
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS. PLUG AND ABANDONMENT	\Box
	MULTIPLE COMPLETION	CASING TEST A CEMENT JOB		/
OTHER:			MIT/Acidize/Return to Inj	X
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.				
05-21-01 MIRU. Tested ann	ulus to 300#. Ok.			
05-23-01 Release pkr & tag bottom @ 2636'. POOH w/ tbg.				
05-24-01 PU 4-1/2" R4 & tested tbg in hole. Set pkr @ 2525' & tested annulus to 340#. (chart attached) RD.				
	ene, 10.7 bbls prod water w/	5 gals TC 420 and 2 dr	ums TC 405. Flush to top perf w/ prod wtr.	
SI. 06-07-01 Swab & flow back load. Acidize w/ 2000 gals 15% Pentol 300 and flush to top perf w/ prod wtr. Flow & swab				
back all load wtr.				
06-08-01 Return well to inject	ction @ 115 BPD @ 900 psi			
/				
I hereby certify that the information a	hove is true and complete to	the best of my knowled	lge and helief	_
Y hereby conting that the mind that	1 /21	, une sest of my interior	Se and series.	
SIGNATURE (I TIT	LE <u>Production Ana</u>	<u>lyst</u> DATE <u>5/2/01</u>	
Type or print name Terri Stathe		Telephone No. 915	/683-7443	
(This space for State use)				
APPPROVED BY RELOYD	only TIT	I F	DATE	
Conditions of approval, if any:	111.		DAIL_	_
11 -, ,	I			