

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

JUN 23 1976

O. C. C.

ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry hole	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator Mountain States Petroleum Corp. V	5. State Oil & Gas Lease No.
3. Address of Operator P O Box 1936 Roswell, New Mexico 88201	7. Unit Agreement Name
4. Location of Well UNIT LETTER A, 660 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 29 TOWNSHIP 12-S RANGE 27E NMPM.	8. Farm or Lease Name Calumet
	9. Well No. #1
	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3583 GR	12. County Chaves

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Completion Attempt <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-15-76 Spotted 1 bbl acid perfs 1754-1809. Set packer at 1727. Acid 3000 gals 15% acid. Swabbed dry with no show of oil or gas.

6-16-76 Swabbed est 5 BAW no shows. Received verbal permission NMOCC at P&A. Intend to recover some 4-1/2" csg. Will plug as follows:

25 sxs in and out of 4-1/2" stub  
25 sxs in and out base 7" csg  
10 sx surface plug with marker.

Prep to P&A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED KC Huenor TITLE Geologist DATE June 21, 1976

APPROVED BY W. A. Gussert TITLE SUPERVISOR, DISTRICT II DATE JUN 24 1976

CONDITIONS OF APPROVAL, IF ANY:

Intervals between plugs filled w/ mud