TEVENS OPERATING CORPORATION

WEEKLY REPORT

Field Wildcat - Penn

İ.

Stevens Operating Corporation

O'Brien C-4 Township 9 South, Range 28 East Section 1:

- 8-08-84 Well loaded up & died overnite, swabbed all day, fluid level maintained 2500# off bttm. Well stabilized @ 20# PSI thru 3/4" choke (est 300 MCFD). Shut in over nite 910# PSI tbg well flowed 30 min thru 1/4" choke before fluid got to surface. Prep to swab test.
 - 8-09-84 Well flowed back 4 hrs and died, made 4 swab runs, fluid level dn to 2000' off bttm. Unset Pkr & trip put of hole, trip back in w/208 jts 2 3/8 x 4.7# tbg & SN set @ 6669' (31' above top perf). Rig up swab bar & make 3 swab runs, lost swab bar & 2000' sand line on last run, SD. Prep to POH & retrieve swab bar & line.
- 8-10-85 NO REPORT, SD BAD WEATHER.
- 8-13-84 SHUT DN (BAD WEATHER). Prep to fish swab bar.
- 8-14-84 POH w/208 jts, strip out 2000' sand line, trip back in w/new SN & 208 jts 2 3/8 tbg set @ 6669'. Rig dn, prep to test.
- 2-06-85 RUPU & prep to frac existing Bough "C" perfs.
- 2-07-85 Pulled 7/8" rods & 2 3/8" x 4.7# tbg out of hole. Ran 205 jts 2 7/8 x 6.5# tbg w/5 1/2" Model "R" Pkr set @ 6605' KB on BOP. Flanged up, prep to frac.
- 2-09-85 Drug tbg & Pkr out of hole (1 broken slip & rubber gone). Ran 4 3/4 swedge w/bumper sub & jars hit & swedged out tight spots @ 5023', 4980'. Trip in w/new 5 1/2 TST Pkr, SD overnite.
- 2-10-85 Ran 205 jts 2 3/8 x 6.5# tbg & 5 1/2 TST Pkr set @ 6605'. Attempt to frac, well communicated, SD. Jar Pkr loose & POH, slips tore off Pkr (stuck thru csg.).