		_	copy	to SF	
Form 9-331 (May 1963)					
(Do not	SUNDRY NOTICES AND REPORTS C use this form for proposals to drill or to deepen or plug bi Use "APPLICATION FOR PERMIT_" for such pr	DN WELLS ack to a different reservoir. oposals.)	6. IF INDIAN, ALLOTT	EE OR TRIBE NAME	
1. OIL WELL X	GAS WELL OTHER		7. UNIT AGREEMENT N		
2. NAME OF OPE	an Oil Corporation & J. Penrod Tole		8. FARM OR LEASE NA McCrea Fede 9. Well NO.		
3. ADDRESS OF	OPERATOR BOX 848, ROSWell, NM 88201 WELL (Report location clearly and in accordance with any	APR 2 8 1978	1 10. FIELD AND POOL,		
 LOCATION OF See also space At surface 	660' FSL & 1980 FWL	O. C. C. ARTESIA, OFFICE	Wildcat 11. SEC., T., R., M., OB SUBVEY OR ABI	BLK. AND	
14, PERMIT NO.	15. ELEVATIONS (Show whether DF, 1872' G.L.	RT, GR, etc.)	Sec. 31-T9S 12. COUNTY OB PARIS Chaves	-R265 bh 13. state NM	
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or			Other Data	
FRACTURE T SHOOT OR A REPAIR WED (Other) 17. DESCRIBE Pro- proposed nent to th Cleaned Of 1411'. C	ABANDON* CHANGE PLANS OFOSED OR COMPLETED OPERATIONS (Clearly state all pertinen work. If well is directionally drilled, give subsurface locat is work.)* Ut to total depth of 1411' on 3/24/ emented w/185 sx. 3/25/78. Tested Perf 1 st./ft. 1295-96, 97, 98, 99 1340-41, 42, 43: 1350-52, 53, 54,	wATEE SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Production (Note: Report results Completion or Recomp t details, and give pertinent dates, ions and measured and true vertice 78. Ran 4½" new J-55 3000 lbs. No drop in ; 1306-07, 10, 11, 12 56. Acidized 2000 ga	t of multiple completion letion Report and Log : including estimated d al depths for all mark 5, 9½ 1b. casi n pressure. 2; 1329-31, 32	CASING ENT* X n on Well orm.) ate of starting any ers and zones perti-	
3/31/78:	Fraced w/60,000 gals. gellew water Installed pump jack. Pumping load		RECEN APR 2 G	ED 1978 JUNL SUNVEY NEW MEXICO	
SIGNED		perator		2/78	
	e for Federal or State office use)	CTING DISTRICT ENGINE		PR 27 1978	
APPROVEI CONRITIO	BIJ			,	

7

*See Instructions on Reverse Side