

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

JUL 28 1976

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O. C. C.
ARTESIA, OFFICE

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. -----	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name -----
2. Name of Operator Managan Petroleum Corporation		8. Farm or Lease Name White
3. Address of Operator P. O. Box 1737-Roswell, New Mexico 88201		9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> , <u>1980'</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>13</u> TOWNSHIP <u>10S</u> RANGE <u>27E</u> NMPM.		10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3800KB		12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal approval was given by Mr. Gressett 7/23/76 to plug the subject well as follows:
Set 100' plugs (7 7/8" hole) @ 6850-6950, 5800-5900, 4250-4350, 2750-2850 & in & out 8 5/8" csg. @ 1610' (1550-1650) plus 10 sx plug & appropriate dry hole marker @ surface w/heavy drilling mud between each plug. Total depth of well is 6995 in Miss. lime. Work to be performed immediately. No csg. to be pulled

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Hugh E. Managan TITLE Vice President DATE 7/24/76
APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE JUL 28 1976
CONDITIONS OF APPROVAL, IF ANY: