

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-1-78

OCT 27 1981

AL. C. E. L.
ARIZONA, TEXAS

NAME OF OPERATOR	
DATE OF NOTICE	
WELL NO.	
WELL	
UNIT	
NAME OF FIELD	
OPERATOR	

1. Indicate type of Lease
State ☐ New ☒

2. State oil & gas Lease No.

SUNDY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR NOTICING TO PLUG OR TO DEFLECT PLUG PARTIAL A DIFFERENT RESERVOIR.
MADE IN U.S.A. PRINTED BY MEXICO CITY FOR SICK INDUSTRIES

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Fred Pool Drilling Co./

Address of Operator

Box 1300 Clovis Star Rt. Roswell, N.M. 88201.

Location of Well

UNIT LETTER ☒ 990 FEET FROM THE south LINE AND 990 FEET FROM

THE W LINE, SECTION 32 TOWNSHIP 10s RANGE 28e

15. Elevation (Show whether DF, RT, GR, etc.)

3762.0 GL

16. County

Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☒
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPER. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well is temporarily abandoned.

Plan to plug as soon as equipment is available.

Proposed plugging procedure:

- 35 sx 1 plug @ 2246 ft. to 2346 ft. (Bottom)
- 35 sx 1 plug @ 1600 to 1700 ft. (Top of San Andres)
- 35 sx 1 plug @ 1200 ft. to 1300 ft. (Top of Queens)
- 35 sx 1 plug @ 350 ft. to 450 ft. (Surface Pipe) & tog)
- 15 sx 1 plug 10 ft. @ the top.

T.O. 8s 2346 ft.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature]

TITLE Landman

DATE 10-27-81

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87504

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

10. Indicate Type of Lease
State ☐ Free ☒

11. State F.D. & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR ANY PROPOSAL TO DEEPEN OR PLUG BACK TO A DEEPER FORMERLY PRODUCING WELL. USE APPLICATION FOR PERMIT TO PLUG BACK OR OTHER APPROPRIATE FORM.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of operator
*** Fred Pool, Drilling Co.**

3. Address of Operator
409 White Bldg. Roswell, N.M. 88201

4. Location of well
UNIT LETTER **M** **990** FEET FROM THE **South** LINE **A** **990** FEET FROM
W LINE SECTION **32** TOWNSHIP **10 S** RANGE **26 E** MAPA.

7. Unit Agreement Name

8. Form of Lease Date
L.E. Minerals

9. Well No.
1

10. Field and Pool, or Wildcat
wildcat

12. County
Chaves

11. Elevation (Show whether DE, RI, GR, etc.)
3762.0 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☒	CHANGE PLANS ☐	COMMENCE DRILLING OHS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
OTHER ☐			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

Well is temporarily abandoned.

Plan to plug as soon as equipment is available.

Proposed plugging procedure:

- ⑤ 155X 1 plug 10 ft. @ the top
- ② 355X 1 plug @ 1600 to 1700 ft. (Top of San Andres)
- ③ 355X 1 plug @ 1200 ft. to 1300 ft. (Top of Queens)
- ④ 355X 1 plug @ 350 ft. to 450 ft. (Surface Pipe) *Flag*
- ① 355X 1 plug @ 2246 ft. to 2346 ft. (Bottom)

T.D. 8s 2346 ft.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE **Secretary** DATE **3-12-80**

APPROVED BY *W.A. Grasset* TITLE **Supervisor, Plugging** DATE **3-12-80**

CONDITIONS OF APPROVAL, IF ANY:
Under the supervision of Plugging

Notary N.M.O.C.C. in official duty to witness
Plugging

OIL CONSERVATION DIVISION
P.O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-1-79

NO. OF EQUIPMENT LOGS	
DISTRIBUTION	
SANTA FE	
PLUG	
UNIT NO.	
NAME OF FIELD	
OPERATOR	

1. Indicate Type of Lease
State ☐ Free ☒

2. State and Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS OCT 30 1981

1. Indicate Type of Well
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Fred Pool Drilling Co.

3. Address of Operator
Box 1300 Clovis Star Rt. Roswell, N.M. 88201

4. Location of Well
UNIT LETTER M 990 FEET FROM THE south 990 FEET FROM

THE W 32 SECTION 10s RANGE 28e

5. Elevation (Show whether DE, RT, GR, etc.)
3762.0 BL

6. County
Chaves

7. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☒	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
REPAIR OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

8. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well is temporarily abandoned.

Plan to plug as soon as equipment is available.

Proposed plugging procedure:

- 35 sx 1 plug @ 2246 ft. to 2346 ft. (Bottom)
- 35 sx 1 plug @ 1600 to 1700 ft. (Top of San Andres)
- 35 sx 1 plug @ 1200 ft. to 1300 ft. (Top of Queens)
- 35 sx 1 plug @ 350 ft. to 450 ft. (Surface Pipe & tog)
- 15 sx 1 plug 10 ft. @ the top.

T.O. 8s 2346 ft.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE _____ DATE 10-27-81

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

