			215/1	
Submit 3 Copies To Appropriate District State of New Mexico			- 71/	Form C-103
Office District I Energy, Minerals and Natural Resources			Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
District II 811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION			30-005-60493 5. Indicate Type of	of Lanca
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		- ·	K FEE	
District IV Santa Fe, INIVI 8/303			6. State Oil & G	
1220 S. St. Francis Dr., Santa Fe, NM 87505			VA-1747	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Caracidus AVE S	·lata
PROPOSALS.)			Cassidy AVF S	laide
1. Type of Well: Oil Well Gas Well X Other		A 25		
2. Name of Operator	, /8 r.i	2 20 20	7. Well No.	· · · · · · · · · · · · · · · · · · ·
Vator Petroleum Corporation / (9) #1				
300 APTECIA			8. Pool name or	1
105 S. 4th Street Artesia, NM 88	3210 🦠 ∋CD	ATT NO	Wildcat Mi	ssissippian
4. Well Location	* * * * * * * * * * * * * * * * * * *	xi, Çi,	<u> </u>	
4. Well Location				
Unit Letter O: 660 feet f	rom the South 1	ine and1980	feet from the	ast line
Section 21 Townshi			NMPM Cho	ives County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3601' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION			SEQUENT REI	
PERFORM REMEDIAL WORK PLUG AN	D ABANDON L	REMEDIAL WORK ALTERING CASING PLUG AND		
	CHANGE PLANS COMMENCE DRILLING OPNS. X ABANDONMENT			
PULL OR ALTER CASING MULTIPLICOMPLE	DMPLETION CEMENT JOB			
OTHER:		OTHER:		
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of				
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or				
recompilation. 7/31/00 – spud re-entry at 10:00 AM with 7-7/8" bit.				
8/1 – 8/2/00 – Drilled out cement plugs and cleaned out hole to 4-1/2" casing stub at 3900'.				
8/4/00 – Ran 7" slip joint and 91 joints of 4-1/2" 10.5# J-55 casing, slip over casing stub at 3900'.				
Cement with 350 sxs 35:65 with 6% gel + 5 pps salt + 1/4 pps celloflake. Tail in with 150 sxs class C + 1% CaCl2.				
8/5/00 - Plug down at 6 AM. WOC until Monday.				
8/7/00 – Drilled out. WOC 48 hours. 8/8 – 8/24/00 – Drill out cement plugs, mill and fish junk in hole to 4946'.				
8/27/00 – Run CCL. Indicates casing not tied together, drilling outside of casing.				
8/29/00 - Set 20 sxs cement plug 4903-4	1689'. Set CIBP at	3850', cap with 3	35' of cement.	
Run CBL. TOC 2640'.				
I hereby certify that the information above is tr	ue and complete to the	best of my knowled	lge and belief.	
SIGNATURE Sixtin thepa				December 27, 2001
				No. 505-748-1471
Type or print name Susan Herpin (This space for State use) Othernal Signature	NED BY TIM W. QU	<u>u</u>	Telephone	
OISTRICT II S	UPERVISOR			JAN 1 0 2002
APPPROVED BY	TITLE			DATE
Conditions of approval, if any:				