

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

MAR 7 1980

**O. C. D.
ARTESIA, OFFICE**

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-5259

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- SI well - Inactive	7. Unit Agreement Name
2. Name of Operator Southland Royalty Company ✓	8. Farm or Lease Name Sams-State
3. Address of Operator 1100 Wall Towers West, Midland, Texas 79701	9. Well No. 2
4. Location of Well UNIT LETTER D 660 FEET FROM THE north LINE AND 660 FEET FROM THE west LINE, SECTION 16 TOWNSHIP 14S RANGE 28E NMPM.	10. Field and Pool, or Wildcat (Gryb) Undesignated (Sams Ranch)
15. Elevation (Show whether DF, RT, CR, etc.) 3571.3'	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-27-80 Rigged up. Killed well with brine water.

2-28-80 Set CIBP @ 1610'. Dump 35' cmt. on plug. Displaced hole with 9.5# mud. Spot cmt. plug from 316-216'. Spot cmt plug from 30' to surface. Clean location. Install dryhole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. Harney Can TITLE District Engineer DATE 3-5-80

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: