OPERATOR //	7 1978  State X Fee 5. State Oil 6 Gas Lease No. K-6998
SUNDRY NOTICES AND REPORTS ON WELLS ARTESIA.  (DO NOT USE THIS FORM FOR PROPOSALS TO DIVIL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RI  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	SEENE
OIL GAS OTHER- P & A	7. Unit Agreement Name
Yates Petroleum Corporation	6. Farm or Lease Name Smith JR State Com
3. Address of Operator	9. Well No.
207 South 4th Street - Artesia, NM 88210	1 1
4. Location of Well  WHIT LETTER L 1980 FEET FROM THE South LINE AND 651	O FEET FROM Wildcat Devonian
THE West LINE, SECTION 14 TOWNSHIP 98 RANGE 20	6ENMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3807 GR	12. County Chaves
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEI	
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.  TD 6457'; PBTD 6433'. MICU. WIH w/Tubing Conveyed Gun, 2-3/8" tubing and Guiberson Uni VI packer, set packer at 6339'. Perforated 6382-6416' w/34 .50" holes as follows: 6382-6385' (6 holes), 6401-6414' (26 holes), 6416' (2 holes) (2 spf). No GTS. Ran swab no fluid in hole. Treated perforations w/1000g 15% DS-30 acid. Swbd w/show of gas. Swbd dn Tripped guns. Retreated perfs w/4000g 20% DS-30 & ball sealers. Swbd dn - show of gas TSTM. Ran swb FL 2000' from surface. WIH w/CIBP set at 6300'. Dmpd 30' of cmt on top of plug. WOC. WIH wCasing Gun and perf. 6205-6210' w/10 .42" holes. POOH. RIH w/Guiberson Uni VI pkr on 2-3/8" tbg set pkr at 6193' and trtd perfs w/500g 15% DS-30 acid. Swbd - water. WIH w/CIBP set at 6150' - dmpd 28' of cmt on top of plug. WOC. WIH w/Casing Gun and perf 6022-28' w/12 .34" holes (Miss.). POOH. WIH w/Guiberson pkron 2-3/8" tbg set pkr at 5981'. Trtd perf w/1500g 15% DS-30 acid. Swbd - show of gas w/wtr. WIH w/CIBP at 4960' & dmpd 25' cmt on top of plug. POOH. WCC. WIH w/Csg Gun, pkr on 2-3/8" tbg, set pkr at 4755'. Perf 4806-10' w/8 .50" holes (2spf). Trtd perfs w/1000b 15% DS-30 acid. Swbd. FL 4000' From surface. Small show of gas TSTM. Sand Fracd perfs w/40000g trtd wtr. 50000# sd, 20000# 100 mesh 30000# 20-40 sd w/ball sealers. Swbd back and all water.	
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNED LULIU TITLE GEOL. Secty  DATE 12-6-78	

SUPERVISOR, DISTRICT II

DEC 1 2 1978