NAME DE C. C. COPT

Cepy to S7

orm 9-331 May 1963)	NITED STATES	SUBMIT IN (Other inst.	'PLICATE'		au No. 42-R1424.
	DEPARIMENT OF THE INTERI GEOLOGICAL SURVEY	IOR verse side)		N M - 1746	AND SERIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)				6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
OIL GAS WELL WE NAME OF OPERATO	OR OTHER	RECE	IVE	7. UNIT AGREEMENT N. 8. FARM OR LEASE NAM Union	
P O Box 1	RATOR ROSWell, New Mexico 8820)]	8 1978	9. WELL NO.	
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* C. C. See also space 17 below.) At surface				10. FIELD AND POOL, OR WILDCAT Comanche	
660' FNL	& 330' FWL			11. SEC., T., B., M., OR SURVEY OR AREA Sec. 14-T]]S-	•
4. PERMIT NO.	15. ELEVATIONS (Show whether DE Approx. 3506 G R	r, RT, GR, etc.)		12. COUNTY OF PARISE	New Mexi
8.	Check Appropriate Box To Indicate N	lature of Notice, R	Report, or O	ther Data	
	NOTICE OF INTENTION TO:		SUBSEQU	ENT REPORT OF:	·

REPAIRING WELL PULL OR ALTER CASING TEST WATER SHUT-OFF ALTERING CASING MULTIPLE COMPLETE FRACTURE TREAT SHOOTING OR ACIDIZING Progress report ABANDONMENT* SHOOT OR ACIDIZE ABANDON* REPAIR WELL CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

09-11-78 Drilling 70'.

Ran 10-3/4" casing to 50'. T D 104'. (plans are to pull 10-3/4" csg. 09-18-78 re-ream hole and run 10-3/4" cas to 100')

Pulled 10-3/4" casing. Reaming hole at 80'. T D 104' 09-25-78

09/26/78

APPROVED BY

ACTING DISTRICT ENGINEER

SEP 28 1978 DATE _