

NO. OF COPIES RECEIVED		3
DISTRIBUTION		
SANTA FE	/	
FILE	/	/
U.S.G.S.		
LAND OFFICE		
OPERATOR	/	

RECEIVED
 NEW MEXICO OIL CONSERVATION COMMISSION
OCT 5 1978
O. C. C.
ARTESIA, OFFICE

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEX OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry		7. Unit Agreement Name
2. Name of Operator Hanagan Petroleum Corporation ✓		8. Farm or Lease Name Faircloth
3. Address of Operator P. O. Box 1737, Roswell, New Mexico 88201		9. Well No. 1
4. Location of Well UNIT LETTER M 660' FEET FROM THE South LINE AND 660' FEET FROM THE West LINE, SECTION 29 TOWNSHIP 7 S RANGE 27 E NMPM.		10. Field and Pool, or Wildcat Wildcat Mountain
15. Elevation (Show whether DF, RT, GR, etc.) 4039 G R		12. County Chaves

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/27/78: T.D. 6766' Plug & Abandonment in this Manner W/Howco Cementing, Class "H" Cement, 35 SX. plugs: 6500-6600', 5350-5450', 3900-4000', 2450-2550', (1310-1410', in & out 8 5/8" csg. @ 1362') 10 SX. Surface Plug W/dry hole marker @ surface no csg. pulled heavy mud between all plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. L. Southerland TITLE Agent DATE 10-4-78

APPROVED BY *[Signature]* TITLE OIL AND GAS INSPECTOR DATE MAY - 3 1979

CONDITIONS OF APPROVAL, IF ANY: