

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# U.S. DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

P. O. BOX 2008

SANTA FE, NEW MEXICO 87501

DEC 10 1979

O. C. C.  
ARTEBIA, OFFICE

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Fred Pool Drlg. Co. ✓		8. Farm or Lease Name Sunshine
3. Address of Operator 327 White Bldg. Roswell 1, N.M. 88201		9. Well No. 2
4. Location of Well UNIT LETTER <u>D</u> <u>990</u> FEET FROM THE <u>N</u> LINE AND <u>330</u> FEET FROM THE <u>W</u> LINE, SECTION <u>10</u> TOWNSHIP <u>11S</u> RANGE <u>28E</u> N.M.P.M.		10. Field and Pool, or Whichever <u>Uni. L. Chisum, S.A.</u>
15. Elevation (Show whether DF, RT, GR, etc.) 3738.72 GL		12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>	
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

December 5, 1978

Ran 2300 ft. tubing, circulated hole with mud.

Set cement plugs: 2300 to 2200 ft.  
1600 to 1500  
1300 to 1200  
400 to 300 ft.

Set 10 sx cement in top of surface pipe.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Pete Pool TITLE Secretary DATE 12-18-78

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: