

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Prazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.
30005-60598

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

Twin Lakes San Andres Unit

7. Well No.

9

8. Pool name or Wildcat

Twin Lakes; San Andres (Assoc)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other

Injection

2. Name of Operator

Concho Oil & Gas Corp.

3. Address of Operator

110 W. Louisiana Ste 410; Midland, Tx 79701

4. Well Location

Unit Letter N : 330 Feet from the South line and 990 feet from the West line

Section 25 Township 8S Range 28E NMPM Chaves County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3926 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Concho Oil & Gas Corp. respectfully requests approval to plug and abandon the TLSAU #9 well according to the following procedure:

1. Notify NMOCD Artesia 24 hrs prior to commencement of procedure.
2. Set 150' cmt plug from 2400-2640'. WOC. Tag.
3. Circ hole w/ mud. 2443'
4. Cut csg @ 1910' & POOH.
5. Set 100' cmt plug @ 1860-1960'. WOC. Tag.
6. Set 100' cmt plug @ 1455-1555'. 1400' to 1500'
7. Set 100' cmt plug @ 720-820'.
8. Circ cmt from 170' to surface.
9. Cut off wellhead & install dry hole marker.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terri Stathem TITLE Production Analyst DATE 9-28-01

Type or print name Terri Stathem Telephone No. 915/683-7443

(This space for State use)

APPROVED BY [Signature] TITLE Field Rep DATE 10-10-01


Conditions of approval, if any:

TLSAU #9

Formerly - O'Brien F #3

Lease No.: 24988 Dist. No.: County: Chaves Field: Twin Lakes San Andres
 Section: 25 Twsp: 8S Range: 28E Unit Ltr: M Location: 330' FSL & 990' FWL
 API No. 30-005-60598

Spud Date: 10/11/79
 TD Date: 10/17/79
 Comp Date: 11/29/79



Original Perf Details: P1: 2543, 43.5, 47, 47.5, 50.5, 51, 53, 53.5, 56, 56.5, 60, 60.5, 62, 64, 65, 65.5, 66, 66.5, 67, 71.5, 72.5, 73, 74, 74.5, 75
 6000 gals 28% acid

Jan-88 Add P1: 2544, 54, 57, 61, 70, 74, 72, 78, 79, 81, 82
 No treatment

Nov-88 Acidized w/ 2500 gals 20% w/ xylene

Operator Concho Oil
Well Twin Lakes SA Unit
Unit N Section 25 Township 2 Range 28
API # 30-005-60598

- Salt gel mud consisting of 10# brine with 25# of gel per barrel must be placed between each plug
- Install Dry Hole Marker

* Notify OCD 24 hrs. prior to any work done

