

OIL CONSERVATION DIVISION

P.O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.O.S.	☒
LAND OFFICE	☒
OPERATOR	☒

RECEIVED

DEC -2 1985

O.C.D.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL OR PLUG BACK TO A DIFFERENT RESERVOIR."

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
Ralph Nix

Address of Operator
P.O. Box 617 Artesia, New Mexico 88210

Location of Well
UNIT LETTER B 330 North 2310
FEET FROM THE LINE AND FEET FROM
East 12 8-S 28-E
THE LINE, SECTION TOWNSHIP RANGE NMPM.

3a. Indicate Type of Lease
State ☐ Fee ☒
3. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name
Pinkie

9. Well No.
1

10. Field and Pool, or Wildcat
Bullseye San andres

15. Elevation (Show whether DF, RT, GR, etc.)
4068' GR

12. County
Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

FORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
AL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANE ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒
OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-9 Plug #1 Spot 120 sacks Class C cement @ 2750', tagged plug @ 1500', displace hole with mud laden fluid and pressure tested plug and casing to 250 psi and held.

11-10 Plug #2 Perforated @ 300', pumped 65 sacks cement to surface between 4½" & 8 5/8" casing and 24 sacks on inside of 4½" to surface.

Post ID-2
12-6-85
PJA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Lytle

TITLE Supervisor - DA&S

DATE 11/19/85

Danell Moore

TITLE Geologist

DATE 12/13/85