

IL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

RECEIVED

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

MAY 23 1980

O. C. D.  
ARTESIA OFFICE

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
L-5242	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry</u>		7. Unit Agreement Name <u>Willow Creek</u>
2. Name of Operator <u>Yates Petroleum Corporation</u>		8. Farm or Lease Name <u>Willow Creek Unit</u>
3. Address of Operator <u>207 South 4th Street-Artesia, NM 88210</u>		9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>4S</u> RANGE <u>25E</u> N.M.P.M.		10. Field and Pool, or Wildcat <u>Wildcat</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3440' GR</u>		12. County <u>Chaves</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

at

TD 6670'; PBTD 2468' - TOH w/ packer/2002'. Rigged up Dialog and ran free point. Found free point at 1555'. Shot off 5½" casing at 1550'. Approval was given by Mr. Bill Gressett of NMOC D at Artesia, New Mexico to plug well as follows: (1st plug) 25 sacks Class C neat 2000-2100'; (2nd plug) 75 sacks Class C 2% CaCl 1400-1600' WOC 2 hours; tagged cement at 1380'. (3rd plug) 35 sacks Class C neat 310-410. Heavy mud placed between each plug. This well will be turned over to a rancher to be used for a water well.

The location will be cleaned, pits filled and ready for inspection.

102-10024  
5-23-80

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Christine Ambrose TITLE Geol. Secty. DATE 5-23-80

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: