

10-27-80

to P & A

40 SX 1425-1525

40 SX over 1300-30

10 SX runway

when re entered plug was
not at stage 8 7/8"

8-7-80 4:20 PM

4'12" - 4385 - 70C 3790

85 - 4891-4344 68-4235

4162-74 BB-4130

4045-4107

255X - 4130

up to 4'12" - 3750

cut & pile 4'12" - 3750

100' wire and 9200

355X - 1850-1950

355X - 1425-1525

876" - 1475 -