

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P.O. BOX 2800

SANTA FE, NEW MEXICO 87501

OCT 31 1980

Form C-103
Revised 10-1-76

State ☒ New Mexico
L-5026

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO ENTER OR TO ENTER OR PLUG PART OF A WELL OR RESERVOIR.
USE "APPLICATION FOR PERMIT TO WORK ON WELL" FOR SUCH PURPOSES.

OIL WELL ☐ GAS WELL ☐ OTHER: Dry hole

Name of Operator

Read & Stevens, Inc. ✓

Address of Operator

P. O. Box 1518, Roswell, New Mexico 88201

Location of Well

UNIT LETTER H 1980 FEET FROM THE North 880

THE East 6 4-S 26-12

3904.5' GR

1. Unit Agreement Date

2. Name of Lease Owner

Camp State

3. Well No.

1

4. Kind and Kind of Well or

Wildcat

5. Name

Chaves

Check Appropriate Box To Indicate Nature of Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

REMEDIAL WORK ☐
CONTINUED OPERATIONS ☐
CASING PULLED OR ALTERED OR
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER

7. Description of Proposed or Completed Operations (Clearly state all pertinent details, well logs, and dates, including estimated date of starting any proposed work) SEE RULE 1103.

Prep to plug and abandon as follows:

Spot 40 sx. plug Class "H" cement 1561' - 1413'
Spot 40 sx. plug Class "H" cement 1376' - 1228'
Spot 20 sx. plug Class "H" cement at surface.
Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed: Shari Davidson

Authorized Agent

10-30-80

APPROVED BY: W.A. Gussert

SUPERVISOR, DISTRICT

NOV 03 1980

CONDITIONS OF APPROVAL, IF ANY: