

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED

APR 14 1980

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-2114
7. Unit Agreement Name
8. Farm or Lease Name Plains State
9. Well No. 11
10. Field and Pool, or Wildcat E. Chisum, S.A.
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS O. C. D.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Fred Pool, Drilling Co.
3. Address of Operator 409 White Bldg. Roswell, N.M. 88201
4. Location of Well UNIT LETTER H FEET FROM THE N LINE AND 330 FEET FROM E LINE SECTION 16 TOWNSHIP 11S RANGE 28 E ANP.M.
15. Elevation (Show whether DF, RT, GR, etc.) 3707.97 G L

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENTATION <input type="checkbox"/>	PERFORATE AND ACIDIZE <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 103.

PERFORATION RECORD
4-3-80 2193-95 3 shots
2198-2201 4 shots
2204-2209 6 shots
2216-18 3 shots
2221-23 3 shots
2229-38 10 shots
2241-44 4 shots
2252-54 3 shots

ACID JOB -- Acidized with 6000 gal. 20% HCL, Using Ball Sealers.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Pool Jones TITLE Secretary DATE 4-11-80

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE APR 15 1980

CONDITIONS OF APPROVAL, IF ANY: