

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fed <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Ralph Nix		8. Farm or Lease Name Union Joy
3. Address of Operator P.O. Box 617, Artesia, New Mexico 88210		9. Well No. #1
4. Location of Well UNIT LETTER <u>L</u> <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>West</u> LINE, SECTION <u>32</u> TOWNSHIP <u>7-S</u> RANGE <u>29-E</u> N.M.P.M.		10. Field and Pool, or Wildcat <del>Wildcat</del>
15. Elevation (Show whether DF, RT, GR, etc.) 4020' GR		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set cast iron bridge plug at 2690' with 35' cement cap - tag plug.
2. Cut and pull casing in the vicinity of 1500' size of cement plug will be determined as to the location of the top of Queen at 1576' and free point. Cement plug to be a minimum of 50' in and 50' out of stub, however plug will be such as to sufficiently cover top of Queen also. Tag plug. Should it become necessary in the event free point is considerably higher than Queen, then in addition to above a cast iron bridge plug inside the 4½ will be set at 1590' with a 35' cement cap. Tag plug.
3. Set 100' cement plug from 400' to 500'. Tag plug.
4. Affidavit of responsibility conversion to water well to be completed by operator and landowner.
5. Proposed work to be completed as soon as well service unit is available. Dowell Well to engineer and supervise setting of plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Ralph Nix</u>	TITLE _____	DATE <u>July 13, 1981</u>
APPROVED BY <u>W.A. Gressett</u>	TITLE <u>SUPERVISOR, DISTRICT 1</u>	DATE <u>JUL 21 1981</u>
CONDITIONS OF APPROVAL, IF ANY:		

Notify N.M.O.C.C. in sufficient time to \_\_\_\_\_  
Pharm