

|                        |   |
|------------------------|---|
| NO. OF COPIES RECEIVED |   |
| DISTRIBUTION           |   |
| SANTA FE               | 1 |
| FILE                   | 1 |
| U.S.G.S.               |   |
| LAND OFFICE            |   |
| OPERATOR               |   |

APR 06 1981

O. C. D.  
ARTESIA, OFFICE

|                                |   |
|--------------------------------|---|
| 5a. Indicate Type of Lease     |   |
| State <input type="checkbox"/> | Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No.   |   |

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|   |  |
|---|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-<br>2. Name of Operator<br>The Harlow Corporation ✓<br>3. Address of Operator<br>600 Petroleum Building, Amarillo, TX 79101<br>4. Location of Well<br>UNIT LETTER L 1650 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 19 TOWNSHIP 8S RANGE 29E N.M.P.M.<br>15. Elevation (Show whether DF, RT, GR, etc.)<br>3939GL | 7. Unit Agreement Name<br>8. Farm or Lease Name<br>O'Brien Fee "19"<br>9. Well No.<br>4<br>10. Field and Pool, or Wildcat<br>Twin Lakes-San Andres Ass<br>12. County<br>Chaves |
|---|--|

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☒  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐  
OTHER ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Perforate 2652-2656' 2 shots per ft with Jumbo Jet.

Treat with 500 g MCA, clean up.

Treat with 1000 g NeFe.

Treat with more acid if indicated.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W.B. LaFon TITLE Production Engineer DATE 4/3/81APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE APR 09 1981

CONDITIONS OF APPROVAL, IF ANY: