

1. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	1	
FILE	1	
U.S.G.S.		
LAND OFFICE		
OPERATOR	1	

NEW MEXICO OIL CONSERVATION COMMISSION  
RECEIVED

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-85

APR 3 1980

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
Miller & Olsen	
9. Well No.	
#1	
10. Field and Pool, or Wildcat	
Undes. Railroad Mtn-SA	
12. County	
Chaves	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DEEPER RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-

2. Name of Operator  
PHOENIX RESOURCES COMPANY

3. Address of Operator  
3524 Northwest 56th, Suite 300, Oklahoma City, Oklahoma 73112

4. Location of Well  
UNIT LETTER 1, 1980' FEET FROM THE South LINE AND 660' FEET FROM  
THE East LINE, SECTION 3 TOWNSHIP 8S RANGE 28E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
3998.5 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set 4½", 10.5#/ft, K-55, ST&C casing at 2710' (GR).
- Cemented with 650 sacks of cement (897 ft³). Calculated TOC at 400'.
- Tested casing to 1500 psi for 30 minutes with no pressure loss.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Tom Wadsworth</u>	TITLE <u>Drilling Manager</u>	DATE <u>April 1, 1980</u>
APPROVED BY <u>W.A. Gussitt</u>	TITLE <u>SUPERVISOR, DISTRICT II</u>	DATE <u>APR 1 1980</u>
CONDITIONS OF APPROVAL, IF ANY:		