

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

JUL 22 1980

O. C. D.
ARTESIAN OFFICE

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator Fred Pool Drlg.		8. Farm or Lease Name Corn 24 Com
3. Address of Operator 437 White Bldg. Roswell, N.M. 88201		9. Well No. 2
4. Location of Well UNIT LETTER N 1980 FEET FROM THE W LINE AND 660 FEET FROM South 24 5-S 24-E TOWNSHIP RANGE N.M.P.M.		10. Field and Pool or Wildcat
15. Elevation (Show whether Dr, RT, GR, etc.) 3915.0 GR		12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> Perforation and Acid Job <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Perforated 3706-26 to 3850-66 1 per foot.

Acidized with 3,000 Gallons of 10 % N.E. Acid

Opened up well and swabbed for 1 hour

Received Approximately 100,000 - 125,000 Cubic Feet of Gas

Intend to Frac. Well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Patte Jones TITLE Secretary DATE 7-21-80

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE JUL 24 1980

CONDITIONS OF APPROVAL, IF ANY: