	_			~!!	
Submit 3 Copies To Appropriate District	ffice Energy Minerals and Natural Descurees			-C15 100	Form C-103
Office				1 Ab	Revised March 25, 1999
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240				WELL API NO.	
<u>District II</u> 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION			30-005-60689	
District III	1220 South St. Francis Dr.			5. Indicate Type of	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			STATE State Oil & G	<del></del>
1220 S. St. Francis Dr., Santa Fe, NM				V-5650	as Lease Ivo.
87505 SUNDRY NOTE	CES AND REPORTS ON	JWELLS			Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Ecuso I valle of	om rigitoment rume.
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				Hook AWX Sto	ate
1. Type of Well:	_				
Oil Well Gas Well X	Other	<u> </u>	7		
2. Name of Operator	/	4,	Aug my	7. Well No.	
Yates Petroleum Corpor	ration '	$\frac{2}{2} \frac{K}{2}$	ECEIVED.	#1 8. Pool name or	Wilder
3. Address of Operator  105 S. 4th Street Artes	sia, NM 88210	· 900	ARTESIA	1	ecambrian
105 3. 4" Sileer Aries	IG, 14W 00210		~~A	Wildcal Fit	ecambilan
4. Well Location				<u> </u>	
Unit Letter <u>G: 1</u>	980 feet from the No	<u>orth</u>	line and	feet from the	East line
Section <b>8</b>	Township 10\$	Range	<b>26E</b>	NMPM <b>Chaves</b>	Country
Section 0	10. Elevation (Show wi				County
		3800			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WOR	RK	ALTERING CASING X
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OPNS. PLUG AND ABANDONME		PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND CEMENT JOB		
OTHER:			OTHER: Perfo	orate, Acidize	X
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of					
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or					
recompilation. 1/8/01 – Move in and rig up. TIH with bit and scraper. Tag PBTD at 6535'. POH.					
1/9/01 – Run GR/CBL/CCL. TOC 2960'. Perf Ordovician 6250-6274', 96 holes, .41" holes.					
1/10/01 - Spot 50 gals 20% IC HCL across perfs. Acidize perfs 6250-6274' with 200 gals IC HCL. Swab.					
1/12/01 – Acidize perfs 6250-6274' with 2400 gals 20% IC HCL. Flowback and swab. 1/22/01 – Perf Ordovician: 6186-6190', 16 holes, 6206-6213' 28 holes, 6220-6224, 16 holes, 6230-6234', 16 holes, .41" holes.					
1/23/01 – Spot 100 gals 20% IC HCL at 6234'. Straddle perfs 6186-6234'. Acidize with 1900 gals 20% IC HCL + 114 balls. Swab.					
1/30/01 – Perf Mississippian cherty lime as follows: 5974-5982', 32 holes, 6008-6018', 40 holes, .41" holes.					
1/31/01 - Spot 50 gals 15% IC HCL at 6020'. Straddle perfs 5974-6018'. Acidize with 1750 gals. 15% IC HCL. Swab.					
2/2/01 – Perf Wolfcamp 5452-5466', 15 holes, 5482-5504', 23 holes, 5518-5548', 31 holes, 5564-5578', 15 holes, .41" holes. 2/6/01 – Spot 125 gals 15% IC HCL. Acidize perfs 5452-5578' with 4000 gals 15% IC HCL + 126 balls. Swab.					
2/13/01 – RD and move off.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE					
Type or print name Susan Herpin Telephone No. 505-748-1471  (This space for State use) ORIGINAL SIGNED BY TIM W. GUM					
(This space for State use)	DISTRICT II SUPER	o. m			AHC 9 7 0004
APPPROVED BY	- w # may 8 5	TITLE_	··		
Conditions of approval, if any:					