STATE OF NEW MEXICO

## ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION ARTESIA DISTRICT OFFICE

BRUCE KING

LARRY KEHOE SECRETARY

May 7, 1980

P.O. DRAWER DD ARTESIA, NEW MEXICO 88210 (505) 746-4861-

748-1283

1

McClellan Oil Corporation Post Office Drawer 730 Roswell, New Mexico 88201

> Re: Jack L #1-M-14-6-27 Chaves County, NM

Gentlemen:

We are returning the enclosed Form C-103 on the subject well for additional information.

Please show the 13 3/8" conductor casing and how it was cemented, show whether or not the cement was circulated to surface on the 8 5/8" and was 6% gel added to Pace-setter Lite cement?

If you have any questions concerning this matter, feel free to contact me.

Sincerely,

W.a. Gresset

W. A. Gressett Supervisor, District II

WAG:ar Encls.

NERGY AND MINER		<u> </u>	CONSERVA	TION DIVIC	101		
DISTROUT	······································		P. O. BOX	-	IOF		Form C-103
BANTA FE		5	SANTA FE, NEW		1		Revised 10-1-
FILE						Sa. Indicate Type	of Leuse
LAND OFFICE						Stote	Fon X
OPERATOR			·			5. Stote Oli 6 Gas	
L							
(DO NOT USE T	SUNDRY	NOTICES	AND REPORTS ON	WELLS	1 ED. 19.		
011	GAB WELL					7. Unit Agreement	11ame
ame of Operator	WELL [A]	OTHER-		мдү - 6	1980	8. Farm or Lease	liame
cClellan Oil	Corporatio	n		• •			
ddress of Operator		<u>[]</u>		• • • •	J	Jack L	
. O. Drawer	730 Roswal		vico 88201	ARTESIA, OF	FICE	1	
ocation of Well	JJU, NUSWEI	I, NEW ME	X100 00201			10. Field and Poo	l, or Wildcat
	M Q	60	FROM THE _South	660		Wildcat	
UNIT LETTER	Q		FROM THEUULLIL	LINE AND	FLET FROM		THITTIN
THE West		14	TOWNSHIP 6-S		E sussi		
int	LINE, SECTION			RANGE	<u>с — мири.</u>		
MMMM	MMMM	15. E	levation (Show whether I	OF, RT, GR, etc.)		12. County	XIIIIIIX
		410	6 G. L. 4119	D. F.		Chaves	
	Check A	ppropriate I	Box To Indicate Na	ature of Notice,	Report or Ot		
	IOTICE OF INT			· ·	-	REPORT CF:	
RFORM REMZDIAL WO	ах 🗌		PLUG AND ABANDON	REMEDIAL WORK		ALTER	NG CASING
MPORANILY AGANDON				COMMENCE DRILLING	OPNS.	PLUG A	ID ABANDONMENT
LL ON ALTER CASING			CHANGE PLANS	CASING TEST AND CE	MENT JOB		_
	البينية		ا سيب				
	· · · ·			OTHER			
DTHER			0			······	[
Describe Proposed work) SEE RULE	or Completed Open 1 103.		state all pertinent deta	ils, and give pertiner			larting any propose
Describe Proposed work) SEE RULE	or Completed Oper 1103. Drilled to	1486'.	Ran 1447' of next Pacesetter Li	ils, and give pertiner W 20 1b., J-1	55,8-5/8"	csq.	
Describe Proposed work) SEE RULE	or Completed Oper 1103. Drilled to Cemented w	1486'. ith 450 s hours dri	Ran 1447' of ne	W 20 1b., J-1 te, 6% gel.	55, 8-5/8" & 200 sx Cl	csg. ass "C", 2% (	CaCl.
Describe Proposed work) see Rule 5/03/80:	or Completed Oper 1703. Drilled to Cemented w Waited 18	1486'. ith 450 s hours dri	Ran 1447' of ne x Pacesetter Li	W 20 1b., J-1 te, 6% gel.	55, 8-5/8" & 200 sx Cl	csg. ass "C", 2% (	CaCl.
Describe Proposed work) see Rule 5/03/80:	or Completed Oper 1703. Drilled to Cemented w Waited 18	1486'. ith 450 s hours dri	Ran 1447' of ne x Pacesetter Li	W 20 1b., J-1 te, 6% gel.	55, 8-5/8" & 200 sx Cl	csg. ass "C", 2% (	CaCl.
Describe Proposed work) see Rule 5/03/80:	or Completed Oper 1703. Drilled to Cemented w Waited 18	1486'. ith 450 s hours dri	Ran 1447' of ne x Pacesetter Li	W 20 1b., J-1 te, 6% gel.	55, 8-5/8" & 200 sx Cl	csg. ass "C", 2% (	CaCl.
Describe Proposed work) see Rule 5/03/80:	or Completed Oper 1703. Drilled to Cemented w Waited 18	1486'. ith 450 s hours dri	Ran 1447' of ne x Pacesetter Li	W 20 1b., J-1 te, 6% gel.	55, 8-5/8" & 200 sx Cl	csg. ass "C", 2% (	CaCl.
Describe Proposed work) see Rule 5/03/80:	or Completed Oper 1703. Drilled to Cemented w Waited 18	1486'. ith 450 s hours dri	Ran 1447' of ne x Pacesetter Li	W 20 1b., J-1 te, 6% gel.	55, 8-5/8" & 200 sx Cl	csg. ass "C", 2% (	CaCl.
Describe Proposed work) see Rule 5/03/80:	or Completed Oper 1703. Drilled to Cemented w Waited 18	1486'. ith 450 s hours dri	Ran 1447' of ne x Pacesetter Li	W 20 1b., J-1 te, 6% gel.	55, 8-5/8" & 200 sx Cl	csg. ass "C", 2% (	CaCl.
Describe Proposed work) see Rule 5/03/80:	or Completed Oper 1703. Drilled to Cemented w Waited 18	1486'. ith 450 s hours dri	Ran 1447' of ne x Pacesetter Li	W 20 1b., J-1 te, 6% gel.	55, 8-5/8" & 200 sx Cl	csg. ass "C", 2% (	CaCl.
Describe Proposed work) see Rule 5/03/80:	or Completed Oper 1703. Drilled to Cemented w Waited 18	1486'. ith 450 s hours dri	Ran 1447' of ne x Pacesetter Li	W 20 1b., J-1 te, 6% gel.	55, 8-5/8" & 200 sx Cl	csg. ass "C", 2% (	CaCl.
Describe Proposed work) see Rule 5/03/80:	or Completed Oper 1703. Drilled to Cemented w Waited 18	1486'. ith 450 s hours dri	Ran 1447' of ne x Pacesetter Li	W 20 1b., J-1 te, 6% gel.	55, 8-5/8" & 200 sx Cl	csg. ass "C", 2% (	CaCl.
Describe Proposed work) see Rule 5/03/80:	or Completed Oper 1703. Drilled to Cemented w Waited 18	1486'. ith 450 s hours dri	Ran 1447' of ne x Pacesetter Li	W 20 1b., J-1 te, 6% gel.	55, 8-5/8" & 200 sx Cl	csg. ass "C", 2% (	CaCl.
Describe Proposed work) see Rule 5/03/80:	or Completed Oper 1703. Drilled to Cemented w Waited 18	1486'. ith 450 s hours dri	Ran 1447' of ne x Pacesetter Li	W 20 1b., J-1 te, 6% gel.	55, 8-5/8" & 200 sx Cl	csg. ass "C", 2% (	CaCl.
Describe Proposed work) see Rule 5/03/80:	or Completed Oper 1703. Drilled to Cemented w Waited 18	1486'. ith 450 s hours dri	Ran 1447' of ne x Pacesetter Li	W 20 1b., J-1 te, 6% gel.	55, 8-5/8" & 200 sx Cl	csg. ass "C", 2% (	CaCl.
Describe Proposed work) SEE RULE 5/03/80: 5/04/80:	or Completed Oper fros. Drilled to Cemented w Waited 18 Drilling a	1486'. ith 450 s hours dri head	Ran 1447' of ne x Pacesetter Li	W 20 1b., J- te, 6% gel. Tested 250	55, 8-5/8" & 200 sx Cl lbs. 30 min	csg. ass "C", 2% (	CaCl.
Describe Proposed work) SEE RULE 5/03/80: 5/04/80:	or Completed Oper 1103. Drilled to Cemented w Waited 18 Drilling a t the information at	1486'. ith 450 s hours dri head	Ran 1447' of ne x Pacesetter Li lled out plug.	W 20 1b., J- te, 6% gel. Tested 250	55, 8-5/8" & 200 sx Cl lbs. 30 min	csg. ass "C", 2% (	CaCl.
Describe Proposed work) SEE RULE 5/03/80: 5/04/80:	or Completed Oper fros. Drilled to Cemented w Waited 18 Drilling a	1486'. ith 450 s hours dri head	Ran 1447' of ne x Pacesetter Li lled out plug. d complete to the best of	W 20 1b., J- te, 6% gel. Tested 250	55, 8-5/8" & 200 sx Cl lbs. 30 min	csg. ass "C", 2% (	CaCl.
Describe Proposed work) SEE RULE 5/03/80: 5/04/80:	or Completed Oper 1103. Drilled to Cemented w Waited 18 Drilling a t the information at	1486'. ith 450 s hours dri head	Ran 1447' of ne x Pacesetter Li lled out plug. d complete to the best of	W 20 1b., J- te, 6% gel. Tested 250	55, 8-5/8" & 200 sx Cl lbs. 30 min	csg. ass "C", 2% (	CaCl.
Describe Proposed work) SEE RULE 5/03/80: 5/04/80:	or Completed Oper 1103. Drilled to Cemented w Waited 18 Drilling a t the information at	1486'. ith 450 s hours dri head	Ran 1447' of ne x Pacesetter Li lled out plug. d complete to the best of	W 20 1b., J- te, 6% gel. Tested 250	55, 8-5/8" & 200 sx Cl lbs. 30 min	csg. ass "C", 2% (	CaCl.
Describe Proposed work) SEE RULE 5/03/80: 5/04/80:	or Completed Oper 1103. Drilled to Cemented w Waited 18 Drilling a t the information at	1486'. ith 450 s hours dri head	Ran 1447' of ne x Pacesetter Li lled out plug. d complete to the best of	W 20 1b., J- te, 6% gel. Tested 250	55, 8-5/8" & 200 sx Cl lbs. 30 min	csg. ass "C", 2% (	CaCl.
Describe Proposed work) SEE RULE 5/03/80: 5/04/80:	or Completed Open 1103. Drilled to Cemented w Waited 18 Drilling a Drilling a	1486'. ith 450 s hours dri head	Ran 1447' of ne x Pacesetter Li lled out plug. d complete to the best of	W 20 1b., J- te, 6% gel. Tested 250	55, 8-5/8" & 200 sx Cl lbs. 30 min	csg. ass "C", 2% (	CaCl.
Describe Proposed work) SEE RULE 5/03/80: 5/04/80:	or Completed Open 1103. Drilled to Cemented w Waited 18 Drilling a Drilling a	1486'. ith 450 s hours dri head	Ran 1447' of ne x Pacesetter Li lled out plug. d complete to the best of	W 20 1b., J- te, 6% gel. Tested 250	55, 8-5/8" & 200 sx Cl lbs. 30 min	csg. ass "C", 2% (	CaCl.