

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	✓
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

AUG 20 1980

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-5029
7. Unit Agreement Name
8. Farm or Lease Name Newmill-State
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS C. D.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS, OFFICE

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P & A
2. Name of Operator Hanagan Petroleum Corporation ✓
3. Address of Operator P.O. Box 1737 Roswell, New Mexico 88201
4. Location of Well UNIT LETTER 0 660 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 27 TOWNSHIP 4 South RANGE 27 East NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3969 KB

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T.D. 6850 granite wash by drillers measurements - Well was plugged & abandoned 7/29/80 (no csg. pulled) in following manner: (Class "H" cmt.) 6738-6838 (35sx), 6500-6600 (35sx), 5940-6040 (35sx), 5300-5400 (35sx), 4550-4650 (35sx), 2500-2600 (35sx), 1300-1400 (35sx), tagged top last plug 1305', 15 sx. plug @ surface w/appropriate dry hole marker w/heavy mud between all plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Hugh E. Hanagan</u>	TITLE <u>Vice President</u>	DATE <u>8/18/80</u>
APPROVED BY <u>Max Swilley</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>JAN 08 1981</u>
CONDITIONS OF APPROVAL, IF ANY:		