Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005- 0	1695
5. Indicate Type of Lease STAT	

P.O. Drawer DD, Artesia, NM 88210	STATE FEE XXXX
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)	7. Leuse Name or Unit Agreement Name
1. Type of Well:  OIL	Twin Lakes San Andres Unit
100	
/	31
Energy Development Corporation  O. C. U.  3. Address of Operator	9. Pool name or Wildcat
3. Address of Operator 1000 Louisiana, Ste. 2900, Houston, Tx 77002 ARTESIA, OFFICE	Truis Joke SA Horac.
4. Well Location	1/11/10/ 314:00 011 1/2
Unit Letter F: 2310 Feet From The North Line and 1	650 Feet From The West Line
Section 31 Township 8 South Range 29 East	NMPM Chaves County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
1/////////////////////////////////////	<u> </u>
Check Appropriate Box to Indicate Nature of Notice,	Report, or Other Data
NOTICE OF INTENTION TO:	JBSEQUENT REPORT OF
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL	ING OPNS. PLUG AND ABANDONMENT *X
PULL OR ALTER CASING CASING TEST AND	CEMENT JOB
OTHER: OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, in	ncluding estimated date of starting any proposed
work) SEE RULE 1103.	
3-1-91: Worked 2-3/8" tbg into btm stub of parted csg at	1814'. Lowered 2-3/8" tbg to PBTD
@ 2880'. PU tbg to 2659'. SD. Waitingon approval	L to P&A.
3-28-91: RU Halliburton. Circ hole f/2659' w/gelled brine mud. Spotted 25 sxs Class "C" cmt w/4% Caclium Chloride f/2659'. PU tbg & rev out f/2311'. WOC. Lowered tbg & tagged	
w/4% Caclium Chloride f/2659'. PU tbg & rev out	1/2311'. WUC. Lowered the & tagged
TOC @ 2438'. Spotted an additional 15 sxs cmt @ 2438'. PU tbg to 1962'. Spotted 2 sxs Class "C" w/4% Calcium Chloride. PU tbg to 1551'. Rev out f/1551'. PU tbg to 1	
Witnessed by Johnny Robinson, Dist. II NMOCD.	o teast poor in tire /p / it is
3-29-91: RU Schlumberger. WIH WL & shot 4 squeeze holes @ 1525'. POOH WL. WIH w/R-4 pkr on	
tbg. Set pkr @ 1425'. Established a rate of 3 BPM @ 750 psi. Pumping gelled brine	
into perfs @ 1525'. POOH w/tbg & pkr. WIH w/cmt retainer on tbg set @ 1425'. Mixed & pumped 50 sxs Class "C" cmt w/2% Calcium Chloride through perfs @ 1525'. Displace	

tbg w/5 bbls fresh water. Stung out of retainer. Rev out. POOH w/tbg & setting tool I hereby certify that the information above is true and complete to the best of my knowledge and belief. DATE 4-15-91 Production Superintendet SIGNATURE TELEPHONE NO 713-750-7314

TYPE OR PRINT NAME

(This space for State Use)

APPROVED BY

Steve Yates

ORIGINAL SIGNED BY

MIKE WILLIAMS

SUPERVISOR, DISTRICT IT

APR 3 0 199;

CONDITIONS OF APPROVAL, F-ANY,