STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	· ·	
	1_	
DISTRIBUTION	I	<u> </u>
SANTA FE	1	
FILE	11	1/
U.S.G.S.		1
LAND OFFICE	1.	
OPERATOR	$+7^{\circ}$	1

Coronado Exploration Corp.

1005 Marquette NW

WELL X

1. Name of Operator

3. Address of Operator

4. Location of Well

OIL CONSERVATION I

BOX 2088
BOX 2088

MB. BY COPIES SCCEIVES			
DISTRIBUTION			P. O. BOX 2088
SANTA FE	1		SANTA FE, NEW MEXI
FILE	1	1	
U.S.G.S.		<u> </u>	
LAND OFFICE	1_		

SUNDRY NOTICES AND REPORTS ON WELLS TO HALL ON TO DEEPEN OF PLUG BACK TO A DUSE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSAL

OTHER-

660

NOTICE OF INTENTION TO:

4				
DIVISION	Form C-103 Revised 10-1-78			
O 87501	RETISED 15-1-70			
JUN 23 1980	Sa. Indicate Type of Leuse State Fee X			
O. C. D.	5. State Oil & Gas Lease No.			
ARTESIA, OFFICE	vinninninnin			
FFERENT RESERVOIR. S.)				
	7. Unit Agreement Name			
	8. Farm or Lease Name			
	Mabel			
	9, Well No.			
	1			
	10. Field and Poel, or Wildcat			
660 FEET FROM	Und. L.E. Ranch SA			
28E				
SE ZOE NMPM.				
R, etc.)	12. County			
	Chaves ()			
Notice, Report or Other Data SUBSEQUENT REPORT OF:				
 3				
. WORK	ALTERING CASING			
E DRILLING OPHS.	PLUG AND ABANDONMENT			
EST AND CEMENT JOB X	··· □			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1709. Corrected Report

Albuquerque, NM 87102

15. Elevation (Show whether DF, RT, G

3744 Gr Check Appropriate Box To Indicate Nature of

North

06-13-80

Set 2195' of 4 1/2" 9.5# casing with a Haliburton pack-off shoe leaving 19' of open hole from 2214' to 2195'. Cemented with 250 sx Dowell self stress cement. Est. top of cement 1500'. Pressured casing to 1200 psi. WOC 30 hrs. Drill out packer shoe.

	i.	
CORONADO EXPLORATION CORP	rites Production Secretary	BATE06-20-80
CONDITIONS OF APPROVAL, IF ANY	TITLE OIL AND GAS INSPECTOR	JUN 2 4 1980