

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-005-60732

5. Indicate Type of Lease

STATE ☐

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

Hanagan Petroleum Corporation

3. Address of Operator

P.O. Box 1737 - Roswell, NM 88202

4. Well Location

Unit Letter H : 2310' Feet From The North Line and 990 Feet From The East Line

Section 35

Township 8S

Range 28E

NMPM

Chaves

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to Plug & Abandon as follows:

Notify NMOC-D-Artesia 24 hours prior to commencing procedure.

- 1) Set CIBP @ approx. 2520' & cap w/35' cement plug (top perf @ 2539').
- 2) Fill hole w/mud & set cement plug across T/San Andres from 1955'-1855' (T/San Andres @ 1905'). \* Perforate 4 1/2" log to 1955' spot Bal. Cont Plug 160' inside & 100' outside
- 3) Fill hole w/mud & Set 160' cement plug from 160' to surface. \* Plug TAP
- 4) Install dry hole marker & clean up location. \* Perforate 4 1/2" log to surface. Circ. CMT to surface.

RECEIVED  
OIL - ARTESIA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Michael G. Hanagan*

TITLE

President

DATE 5/13/98

TYPE OR PRINT NAME

Michael G. Hanagan

TELEPHONE NO. 505/623-5053

(This space for State Use)

APPROVED BY

*Michael G. Hanagan*

TITLE

Field Rep. II

DATE

May 22 1998

CONDITIONS OF APPROVAL, IF ANY: