				~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
Submit 3 Copies To Appropriate District  Office  State of New M				< b0	Form C-103
District I	Energy, Minerals and Natural Resources			WELL API NO.	Revised March 25, 1999
District II	OIL CONSERVATION DIVISION			30005-60767	
District III 2040 South Pacheco			5. Indicate Type, STATE	of Lease  X FEE	
District IV Santa Fe, NM 87505				Gas Lease No.	
2040 South Pacheco, Santa Fe, NM 87505  SUNDRY NOTICES AND REPORTS ON WELLS				7 Lease Name o	or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					-
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				Twin Lakes San	Andres Unit
1. Type of Well: Oil Well Gas Well ☐ Other Injection					
2. Name of Operator	<u> </u>	<u> </u>		7. Well No.	
Concho Oil & Gas Corp.  3. Address of Operator				8. Pool name o	49 r Wildcat
110 W. Louisiana Ste 410; Midland,	Tx 79701	****		Twin Lakes; San	
4. Well Location					
Unit Letter N: 560	Feet from the Sou	<u>ıth</u> lir	ne and <u>1650</u> f	eet from theV	Vest line
Section 31	Township		Range 28E	NMPM	Chaves County
	10. Elevation (Show 3997.2 GR	whether DI	R, RKB, RT, GR, et	tc.)	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUB				SEQUENT <u>R</u> E	PORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDO	N L	REMEDIAL WOR	RK □	ALTERING CASING
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING  MULTIPLE			CASING TEST A	ND 🗀	
COMPLETION					
OTHER:	Longrations (Clearly	state all per		cidize & return to pr	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.					
05-21-01 POH w/ rods & pu	mp. Tagged TD @ 28	881'. POH	w/ tbg. TIH w pkr	& set @ 2625'. Dr	copped SV & tested tbg to
2500#. Tested annulus to 300#.					
prod wtr. SI.					
06-04-01 Swab & flow back 06-05-01 Flow & swab back	load. Acidize w/ 200 all load wtr. POOH v	0 gals 15% w/ pkr. TIH	Pentol 300 and flu w/prod tbg & rod	sh w/12.2 bbls prod ls. Return well to p	l wtr. roduction
		p	· ··· Process		A 39
06-07-01 Test: 14.5 BO, 275	5 BW.				All the second of the second o
					TAN PROFIVE
					OCN ARTESIA
	1	1	1 4 C 1 1-	3 11 . 1: . 6	1 (h)
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE   MU	Jakh	TITLE_	Production And	dlyst DATE_	6-11-01
Type or print name Terri Statho			Telephone No. 91	5/683-7443	
(This space for State use)					
APPPROVED BY Conditions of approval, if any:	of Unity	TITLE			DATE 6-12-01