	L CONSERVATION DIVISION	
DISTRIBUTION	P. O. BOX 2088	Form C-103
BANTA FE	SANTA FE, NEW MEXICO 37501	Revised 10-1-3
FILE		5a. Indicate Type of Leise
U.S.O.S.	00T d 0 198	State Foo X
LAND OFFICE		
OPERATOR		5, State Oll 6 Cas Lease 200
······		mmmmm
DO NOT USE THIS FO	SUNDRY NOTICES AND REPORTS ON WELLS	
		7. Unit Agreement Name
WELL X WEL	СТНСЯ-	
Name of Operator		8, Farm or Lease Name
RALPH NIX		Marilun
Address of Operator	Υ	Marilyn 9. Well No.
•	17 Artonia New Merrise 00010	3. WEIT NO.
	517, Artesia, New Mexico 88210	L
Location of Well		10. Field and Pool, or Wills ?
M		Und. railroad mt
West	INE, SECTION 35 TOWNSHIP 7-S RANGE 28-E NMPM.	
THE MESE	INE, SECTION TOWNSHIP TO RANGE ZOTE NMPM.	
mmmm		<u> </u>
	15. Elevation (Show whether DF, RT, GR, etc.	12. County
	3999 GL	Chaves
ERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK COMMENCE IP VG OPNS. CHANGE PLANS CASING TEST AND CEMENT JOB	ALTERING CASING
		Г
ÔTHE B	OTHER	L_
01MER		
. Describe Proposed or Co	mpleted Creations (Clearly state all pertinent details, and give rement dates, including	estimated date of starting any propose
	mpleted Cretations (Clearly state all pertinent details, and give rement dates, including	estimated date of starting any propose
. Describe Proposed or Co workj see Rule 1103.		estimated date of starting any propose
Describe Proposed or Co work) SEE RULE 1103. 10/14/80	Moved on location.	estimated date of starting any propose
Describe Proposed or Co work) see RULE 1103. 10/14/80 10/15/80	Moved on location. Spudded at 8:15 AM.	
Describe Proposed or Co work) SEE RULE 1103. 10/14/80	Moved on location. Spudded at 8:15 AM. Ran 402' of 8 5/8", 20# casing. Cemented with	1
Describe Proposed or Co work) SEE RULE 1103. 10/14/80 10/15/80	Moved on location. Spudded at 8:15 AM. Ran 402' of 8 5/8", 20# casing. Cemented with 200 sx of Class C with 3% CACL. Circulated 40	1
Describe Proposed or Co work) SEE RULE 1103. 10/14/80 10/15/80 10/16/80	Moved on location. Spudded at 8:15 AM. Ran 402' of 8 5/8", 20# casing. Cemented with 200 sx of Class C with 3% CACL. Circulated 40 sx to pit. Plug down at 1:10 PM.	1
Describe Proposed or Co work) SEE RULE 1103. 10/14/80 10/15/80 10/16/80 10/17/80	Moved on location. Spudded at 8:15 AM. Ran 402' of 8 5/8", 20# casing. Cemented with 200 sx of Class C with 3% CACL. Circulated 40 sx to pit. Plug down at 1:10 PM. WOC 18 hours, tested 1000# for 30 mins. No le	aks.
Describe Proposed or Co work) SEE RULE 1103. 10/14/80 10/15/80 10/16/80	Moved on location. Spudded at 8:15 AM. Ran 402' of 8 5/8", 20# casing. Cemented with 200 sx of Class C with 3% CACL. Circulated 40 sx to pit. Plug down at 1:10 PM. WOC 18 hours, tested 1000# for 30 mins. No le Ran 2691' of 5½' J55, 15.5# casing. Set and c	aks. cemented
Describe Proposed or Co work) SEE RULE 1103. 10/14/80 10/15/80 10/16/80 10/17/80	Moved on location. Spudded at 8:15 AM. Ran 402' of 8 5/8", 20# casing. Cemented with 200 sx of Class C with 3% CACL. Circulated 40 sx to pit. Plug down at 1:10 PM. WOC 18 hours, tested 1000# for 30 mins. No le Ran 2691' of 5½' J55, 15.5# casing. Set and c at 2691' with 200 sx of 50/50 poz with 5# KCL,	eaks. cemented 2%
Describe Proposed or Co work) SEE RULE 1103. 10/14/80 10/15/80 10/16/80 10/17/80	Moved on location. Spudded at 8:15 AM. Ran 402' of 8 5/8", 20# casing. Cemented with 200 sx of Class C with 3% CACL. Circulated 40 sx to pit. Plug down at 1:10 PM. WOC 18 hours, tested 1000# for 30 mins. No le Ran 2691' of 5½' J55, 15.5# casing. Set and c at 2691' with 200 sx of 50/50 poz with 5# KCL, gel. 500 gals. of mud flush and 5 gals. of mo	eaks. cemented 2%
Describe Proposed or Co work) SEE RULE 1103. 10/14/80 10/15/80 10/16/80 10/17/80	Moved on location. Spudded at 8:15 AM. Ran 402' of 8 5/8", 20# casing. Cemented with 200 sx of Class C with 3% CACL. Circulated 40 sx to pit. Plug down at 1:10 PM. WOC 18 hours, tested 1000# for 30 mins. No le Ran 2691' of 5½' J55, 15.5# casing. Set and c at 2691' with 200 sx of 50/50 poz with 5# KCL,	eaks. cemented 2%
Describe Proposed or Co work) SEE RULE 1103. 10/14/80 10/15/80 10/16/80 10/17/80	Moved on location. Spudded at 8:15 AM. Ran 402' of 8 5/8", 20# casing. Cemented with 200 sx of Class C with 3% CACL. Circulated 40 sx to pit. Plug down at 1:10 PM. WOC 18 hours, tested 1000# for 30 mins. No le Ran 2691' of 5½' J55, 15.5# casing. Set and c at 2691' with 200 sx of 50/50 poz with 5# KCL, gel. 500 gals. of mud flush and 5 gals. of mo	eaks. cemented 2%
Describe Proposed or Co work) SEE RULE 1103. 10/14/80 10/15/80 10/16/80 10/17/80	Moved on location. Spudded at 8:15 AM. Ran 402' of 8 5/8", 20# casing. Cemented with 200 sx of Class C with 3% CACL. Circulated 40 sx to pit. Plug down at 1:10 PM. WOC 18 hours, tested 1000# for 30 mins. No le Ran 2691' of 5½' J55, 15.5# casing. Set and c at 2691' with 200 sx of 50/50 poz with 5# KCL, gel. 500 gals. of mud flush and 5 gals. of mo	eaks. cemented 2%
Describe Proposed or Co work) SEE RULE 1103. 10/14/80 10/15/80 10/16/80 10/17/80	Moved on location. Spudded at 8:15 AM. Ran 402' of 8 5/8", 20# casing. Cemented with 200 sx of Class C with 3% CACL. Circulated 40 sx to pit. Plug down at 1:10 PM. WOC 18 hours, tested 1000# for 30 mins. No le Ran 2691' of 5½' J55, 15.5# casing. Set and c at 2691' with 200 sx of 50/50 poz with 5# KCL, gel. 500 gals. of mud flush and 5 gals. of mo	eaks. cemented 2%
Describe Proposed or Co work) SEE RULE 1103. 10/14/80 10/15/80 10/16/80 10/17/80	Moved on location. Spudded at 8:15 AM. Ran 402' of 8 5/8", 20# casing. Cemented with 200 sx of Class C with 3% CACL. Circulated 40 sx to pit. Plug down at 1:10 PM. WOC 18 hours, tested 1000# for 30 mins. No le Ran 2691' of 5½' J55, 15.5# casing. Set and c at 2691' with 200 sx of 50/50 poz with 5# KCL, gel. 500 gals. of mud flush and 5 gals. of mo	eaks. cemented 2%
Describe Proposed or Co work) SEE RULE 1103. 10/14/80 10/15/80 10/16/80 10/17/80	Moved on location. Spudded at 8:15 AM. Ran 402' of 8 5/8", 20# casing. Cemented with 200 sx of Class C with 3% CACL. Circulated 40 sx to pit. Plug down at 1:10 PM. WOC 18 hours, tested 1000# for 30 mins. No le Ran 2691' of 5½' J55, 15.5# casing. Set and c at 2691' with 200 sx of 50/50 poz with 5# KCL, gel. 500 gals. of mud flush and 5 gals. of mo	eaks. cemented 2%

18. I hereby certify that the information above is true and comp	plete to the bost of my knowledge and belief.	- <u>-</u> -
IGNED / Talph / lix g.	Operations Manager	DATE 10/29/80
PROVED IN W. a. Aresset	SUPERVISOR, DISTRICT II	NOV 0 3 1980

CONDITIONS OF APPROVAL, IF ANY: